

AH LIM MOTOR COMPANY

176 Sin Ming Drive #05-12 Sin Ming Autocare Singapore 575721
TEL: 6456 3637 FAX: 6456 3686 Email: admin@almsm.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : TAN CHER HOO
7 TAI HWAN CLOSE

SINGAPORE 555643

Estimate No: MCS1900794

Date: 21 Dec 2022

Policy No: CN012994

Veh Reg No: SDD727T

Make/Model: MAZDA 3

ATTN:

Your Ref No: SDD727T


Claim Type: Third Party

Accident Date: 13/12/2022

TP Veh Reg No: SML5983M

Estimate Repair Cost to Vehicle No :SDD727T

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
SPARE PARTS			
1 REAR FENDER LH (CHECK PRICE)	1 PC	1,233.10	
2 TAI LAMP PANEL LH (CHECK PRICE)	1 PC	396.70	
3 TAILAMP LH	1 PC	534.90	
4 REAR BUMPER (CHECK PRICE)	1 PC	1,138.60	
5 REAR BUMPER SIDE RETAINER LH/RH	2 PC	76.00	
6 REAR BUMPER CLIP	15 PC	45.00	
7 REAR BUMPER RELFECTOR LH	1 PC	53.00	
8 REAR BUMPER WHEEL SPLASH SEAL LH	1 PC	83.20	
9 TAIL END PANEL	1 PC	530.40	
10 REAR FENDER AIR VENT LH (CHECK PRICE)	1 PC	74.90	
11 REAR BUMPER TOWING COVER	1 PC	36.40	
12 REVERSE LAMP LH	1 PC	278.30	
13 REAR WINDSCREEN MOULDING	1 PC	77.00	
		4,557.50	
	Less 10%	455.75	4,101.75
Special Nett			
14 REVERSE SENSOR 1 SET	1 PC	220.00	
15 WINDSCREEN SEALANT	2 PC	30.00	
		250.00	250.00
LABOUR			
16 TO CHECK WIRING	1 PC	20.00	
17 TO DISMANTLE AND INSTALL REAR WINDSCREEN	1 PC	120.00	
18 TO DISMANTLEAND INSTALL REAR BOOT INNER TRIM COVER, REAR SEAT AND SEAT BELT	1 PC	80.00	
19 TO DISMANTLE AND REPLACE DAMAGE PARTS, TO CUT AND WELD REAR FENDER LH, KNOCK AND REPAIR REAR CABIN FLOOR PANEL AND AFFECTED AREA	1 PC	1,150.00	
20 TO SPRAY REAR FENDER LH, REAR BUMPER, TAIL END PNEL AND APPLY SEALANT	1 PC	850.00	
		2,220.00	2,220.00



AH LIM MOTOR COMPANY

176 Sin Ming Drive #05-12 Sin Ming Autocare Singapore 575721
TEL: 6456 3637 FAX: 6456 3686 Email: admin@almsm.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : TAN CHER HOO
7 TAI HWAN CLOSE

SINGAPORE 555643

Estimate No: MCS1900794
Date: 21 Dec 2022
Policy No: CN012994
Veh Reg No: SDD727T
Make/Model: MAZDA 3

ATTN:
Your Ref No: SDD727T
Claim Type: Third Party
Accident Date: 13/12/2022
TP Veh Reg No: SML5983M

Estimate Repair Cost to Vehicle No :SDD727T

Description	Quantity	List Price	Amount
		S\$	S\$
		Total	S\$ 6,571.75
		Add GST @ 7%	460.02
		Total Amount Payable	S\$ 7,031.77

TOTAL: SINGAPORE DOLLAR SEVEN THOUSAND THIRTY ONE AND CENTS SEVENTY SEVEN ONLY

For AH LIM MOTOR COMPANY


AUTHORISED SIGNATURE

INSURER ENQUIRY

Find insurer

Vehicle reg. no.

SML5983M

Date of
Accident

21/12/20 

Reset

% RESULT & RECEIPT

TP Insurer Enquiry

Insurance **China Taiping Insurance (Sing...**

Period of Insurance **28/11/2022 - 27/11/2023**

Requested By **MEILI TAN (AH LIM MOTOR CO...**

Requested Date **21/12/2022 13:46**

Payment details

Request Amount: **S\$1.87**

GST Amount: **S\$0.13**

Total Amount Due (GST
Inclusive): **S\$2**

General Insurance Association

Records Management Centre

GST Registration

No: **M400017735**