

(08/11/13) web  
ASS. REC. BY:

Rasul

REF: CS/SMR 22012984/Ray3

423p

### ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: YN 40022

at Workshop m/s

of 245, JLN AHMAD BRAHIM

Insured:

Policy No.

Claims No. BUS/12/22/7016

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est Repairs:

7

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

REPAIR LIMIT - 7.5K

Veh No:

YN 40022

Yr Regn:

2013, Buh

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MITSUBISHI P83BEA

c.c. 2977

Colour

BLUE

A/C:

Insured / Std / NI / NA

Sp. Reading

39980

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

P83BEA21126

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Air / S/Rim / STD A/Rim or

Tyre Size:

F:

7.00R16

R:

dp

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

GT RADIAL

Front

Rear

R/Bal.

7

mm

R/Bal.

7h

mm

L/Bal.

7

mm

L/Bal.

7h

mm

D.O.A.

22/12/22

D.O.I.

04/01/23

Survey held at

LYS ENGINEERING

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

ESTIMATE RANGE OF REPAIR / NO. OF DAYS -

Rasul confirmed lump sum: \$4900 and 7 days  
(red, \$8800, 64%)

Date/Time, File Pass to?

1) 20/03/23

Date/Time, File Return to?

2)

☐

: Prell. Report

☐

: Final Report

Days Of Repair: 7

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

) \$ + RS \$

) Photos

) Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format :

tp

Lump Sum / I.B.I.: (\$

4900