



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

HSBC LIFE (SINGAPORE) PTE LTD
10 MARINA BOULEVARD #48-01 MARINA BAY
FINANCIAL CENTRE TOWER 2 SINGAPORE
018983
ATTN: OH VALE

Ref: CS/ASM22012985/Tnp3m4

Date: 27/03/2023

Code: HSB

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 8511Z	Veh. Inspected	SG 5182M
Policy No.	VFX/P2419140	Coverage (\$)	0.00
Claim No.	S2M04GSB	Excess (\$)	0.00
Assign From	OH VALE	Assign Date	29/12/2022

2. Vehicle Particulars & Condition

Make & Model	VOLVO B9TL	c.c	9364
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	YV3S4P920GA175168	Colour	BLUE
Odometer	415818 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	275/70R22.5	BRIDGESTONE	8 mm
L/H Front Tyre	275/70R22.5	BRIDGESTONE	8 mm
R/H Rear Tyre	275/70R22.5 (D)	BRIDGESTONE	8/8 mm
L/H Rear Tyre	275/70R22.5 (D)	BRIDGESTONE	8/8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	18/12/2022	Inspection Date	30/12/2022
Survey held at	3 YIO CHU KANG CRESCENT ROAD, SINGAPORE 786010		
Repairer	SBS TRANSIT LTD (HQ)		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **2 Working Days**