

Accident Repair Estimate

Accident Date: 18/12/2022 Bus Registration Number: SG 5182 M
 Accident Time: 1305 HRS Bus Type: Volvo B9TL Eu5, DD, AC, 3 Axle
 Accident Report Number: AR-2022-4231 Date of Survey: 30/12/2022
 3rd Party Claim against: SHD 8511 Z TAXI Date of Registration: 02/01/2016

Section A

Parts and Material Cost

No.	Parts or Item Description	Unit Price	Quantity	Total Cost
1	LED LICENSE PLATE LAMP	\$ 21.00	2	\$ 42.00
2	NUMBER PLATE RECESS PAN;EXT.RR	\$ 168.00	1	\$ 168.00
3	RUBBER BUFFER;EXTERIOR REAR	\$ 48.00	1	\$ 48.00
4	PANEL.REAR BUMPER.O/S	\$ 160.00	1	\$ 160.00
5	SPRAY PAINT- GREEN;600ML;SG BUS	\$ 0.05	600	\$ 30.00
6	SIKAFLEX 255 EXTRA BLACK (400 ML/SAU)	\$ 12.50	1	\$ 12.50
7	POLYESTER PUTTY KANDE (2.5LT)	\$ 17.50	1	\$ 17.50
Total Parts & Material Cost				\$ 478.00

Section B

Assessment/Repair/Spray paint (labour Cost)

NO.	Description	Cost
1	TO REMOVE / REPLACE / REPAIR DAMAGE PARTS / ASSESSMENT BY WORKSHOP	\$ 188.00
2	TO REMOVE / REPLACE / REPAIR DAMAGE PARTS BY CONTRACTOR	\$ 750.00
3	TO REMOVE / REPLACE / REPAIR DAMAGE ADVERTISEMENT/GREEN LIVERY PANEL	\$ 100.00
Total Labour Cost		\$ 1,038.00

Section C

Summary

NO.	Description	Cost	Notes
1	TOTAL REPAIR COSTS	\$ 1,516.00	
2	TOTAL DOWNTIME (DAYS)	\$ 842.62	2 DAILY RATE-WSD=\$421.31
3	TOWING COST	\$ -	
4	TOTAL OVERHEADS COSTS = TOTAL REPAIR COST x 30%	\$ 454.80	
TOTAL COST		\$ 2,813.42	

SURVEYOR ACCEPTANCE

NAME: _____
 DATE: _____
 SIGN: _____
 HP NO: _____
 E-MAIL: _____
 COMPANY: _____

SBST VERIFICATION

Nurizman Yusoff
 Technical Officer
 (DID) 63754264/ (HP) 84256323 | nurizmanby@sbstransit.com.sg
 Bus Engineering | Seletar Depot
 3 Yio Chu Kang crescent(S786010)

SBS Transit



A member of COMFORTDRIVE

NURIZMAN BIN YUSOFF
 TECHNICAL OFFICER
 SELETAR BUS WORKSHOP

31 DEC 2022