



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: S2M03PY3

Date: 09th Feb 2023

Our Ref: CS3/ASM22000163/Tqp3e2-1

M/s HSBC Life (Singapore) Pte Ltd

10 Marina Boulevard

#48-01 Marina Bay Financial Centre Tower 2

Singapore 018983

(The Motor Claims Department)

Attn: Ho Winnie

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: GX 2326M
INSURED VEHICLE: PC 2410G
ACCIDENT DATE: 31/12/2021**

We thank you for your instruction on 28/12/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of GX 2326M from M/s Pro Plus Automobile Engineers.
- b) Singapore Accident Statement and Police Report of Vehicles GX 2326M and PC 2410G.
- c) Final Repair Bill of GX 2326M from M/s Koo Ah Whar.
- d) Colour damaged vehicle photographs of GX 2326M.

Pre-Repair Inspection Date: 05/01/2022 at M/s 5 Soon Lee Street #06-03 Pioneer Point, Repairer: Koo Ah Whar.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: GX 2326M
Make & Model	: Toyota Hiace Diesel
Year of Registration	: 2004
Chassis Number	: LH1621010808
Engine Capacity	: 2986 cc

2. We recommend that the repairs of the entire damage require about 10 (Ten) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.