



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)		Ref:	CS/SPF22012991/Uny3m4
ACCIDENT CLAIMS SECTION (SPORE POLICE FORCE) POLICE LOGISTICS BASE (PLB) 1		Date:	11/01/2023
HEMMANT ROAD SINGAPORE 438675			
ATTN: HAFIZUL FARHAN		Code:	SPF
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	QX 604E	Veh. Inspected	SNC 8056E
Policy No.		Coverage (\$)	0.00
Claim No.	ACS/105/009/2022/112	Excess (\$)	0.00
Assign From	HAFIZUL FARHAN	Assign Date	29/12/2022
2. Vehicle Particulars & Condition			
Make & Model	MERCEDES BENZ C 180 (A)	c.c	1597
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	WDD2040452A644362	Colour	BLACK
Odometer	147866 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/40ZR18	MICHELIN	6 mm
L/H Front Tyre	225/40ZR18	MICHELIN	6 mm
R/H Rear Tyre	225/40ZR18	MICHELIN	6 mm
L/H Rear Tyre	225/40ZR18	MICHELIN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.			
DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	27/12/2022	Inspection Date	03/01/2023
Survey held at	SUPER-ZEE MOTOR SERVICE BLK 14 DEFU LANE 10 #01-402 SINGAPORE 539195		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	