

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SNC 8056E

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent?: Yes or No

Consistent?: Yes or No

days Res.: Yes or No

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Yr Regn:

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Dep/OK.

have video for use 19-12-2031

SNC 8056E 6799E

7/1/23 1/5 @ 1400 insured Christine (paid \$6549, 82%)
range \$1400 - \$1600

Date/Time, File Pass to?

☐

Preli. Report

1) 10/01/2023

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / L.B.I. (\$) 1400

TOTAL

SUPER-ZEE MOTOR SERVICE

BLK 14 DEFU LANE 10 #01-402 SINGAPORE 539195 TEL: 6383 1913 FAX: 6383 9565
EMAIL: superzeemotor@gmail.com

3 Jan 2023

SPF Accidents Claims Section
Automotive Engg & Mgmt Division
Police Logistics Department
No 1 Mount Pleasant Road
Blk 8 Old Police Academy #02-12
Singapore 298333

not Accident
net
3/1/23
take photo after repair
3 days
2/5 to 1400

THIRD PARTY CLAIM

OWNER NAME : LAU WEI CHENG
VEHICLE REG NO : SNC8056E
DATE OF ACCIDENT : 27 DEC 2022
PLACE OF ACCIDENT : PIE (SLIP ROAD EXIT TO LORNIE ROAD)
INVOLVING VEH NO : QX604E

We append herewith our estimate for the repairs of SNC8056E as follows:

Materials Required

1 pc Rear RH Fender
1 pc Rear RH Door
1 pc Rear RH Tyre Rim
1 pc Rear RH Tyre

2
2
cut
800
S\$2,513.00 X
S\$2,626.00 X
S\$ 650.00 ✓ S/W
S\$ 480.00 X

S\$6,269.00

Labour Charge

To dismantle & replace damaged parts, panelbeat where necessary S\$ 450.00 400
To remove/refit rear windscreen to facilitate change of rear fender S\$ 150.00 11 X
To transfer door components S\$ 60.00 11 X
To putty, apply primer & spraypaint Rear RH door and fender S\$ 900.00 700
And Rear Bumper S\$ 120.00 X
To apply rustproofing on repaired, replaced panel 11

S\$7,949.00
=====

SUPER-ZEE MOTOR SERVICE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Insurance claim on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
- Is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: