



Main Office : No. 22, Jalan Kilang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 1008, Bukit Merah Lane 3,
#01-04/06/08/115, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0088864-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise In Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre
Hilton Auto Trading
Dealing In New/Used Cars, Hire Purchase & Insurance.



TP INSURER: India International Insurance Pte Ltd (HQ)
ER BENG HUI

Singapore

Claimant Insurer: Income Insurance Limited

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	23/12/2022
Vehicle Reg. No.:	SMU467Y	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	ER BENG HUI		
Make/Model:	TOYOTA CAMRY, 2.5 (A)	Vehicle Reg. Date:	28/07/2020
Vehicle Colour:	SILVER	Chassis No:	AXVH701039735
Engine No:	A25A5118692		
Odometer:	0 KM		
Paint Type:			
List Item Discount:	25.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	20		
Description of Accident/Loss	REFER TO SKETCH		
Remarks:	VEHICLE AT 15 FAN YOONG ROAD.		
Present Location:	MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)		

COST OF CLAIMS	Amount
Parts	15,714.17
Miscellaneous Items	11.00
Labour	5,590.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	21,315.17
+ GST 7.00% (S\$)	1,492.06
Nett Amount (S\$)	22,807.23

This claim is handled by: BRIAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS		
Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Dec 2022)
Parts:	143	TOYOTA CAMRY 2.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	Mova Automotive Pte Ltd/SMU467Y/28/12/2022 18:36	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR WINDSCREEN SEAL	25.00	0.00	*95.00 FL
2	1		*BOOT LID	25.00	0.00	*1,580.90 FL
3	2		*BOOT LID HINGE LH/RH	25.00	0.00	*317.00 FL
4	1		*BOOT LID INNER TRIM	25.00	0.00	*390.90 FL
5	10		*BOOT LID INNER TRIM CLIPS	25.00	0.00	*55.00 FL
6	1		*BOOT LID WEATHERSTRIPS	25.00	0.00	*258.50 FL
7	1		*TOYOTA LOGO - HYBRID	25.00	0.00	*95.00 FL
8	1		*BOOTLID HANDLE TRIM	25.00	0.00	*215.30 FL
9	1		*BOOT LID HANDLE TRIM SEAL	25.00	0.00	*45.30 FL
10	1		*LOWER BOOT LID TRIM	25.00	0.00	*105.80 FL
11	2		*NUMBER PLATE LAMP LH/RH	25.00	0.00	*361.00 FL
12	1		*BOOT LID LOCK HANDLE	25.00	0.00	*165.80 FL
13	1		*CAMRY EMBLEM	25.00	0.00	*79.80 FL
14	1		*SYNERGY EMBLEM	25.00	0.00	*80.50 FL
15	2		*TAILLAMP INNER LH/RH	25.00	0.00	*1,490.60 FL
16	2		*TAILLAMP INNER GASKET LH/RH	25.00	0.00	*70.00 FL
17	2		*TAILLAMP OUTER LH/RH	25.00	0.00	*1,961.00 FL
18	2		*TAILLAMP MOUNTING CLIPS	25.00	0.00	*17.00 FL
19	2		*TAILLAMP LOWER BRACKET LH/RH	25.00	0.00	*151.60 FL
20	1		*TAILLAMP SIDE TRIM LH/RH	25.00	0.00	*49.30 FL
21	1		*REAR BUMPER	25.00	0.00	*856.50 FL
22	2		*REAR BUMPER RETAINER LH/RH	25.00	0.00	*217.40 FL
23	10		*REAR BUMPER CLIPS	25.00	0.00	*55.00 FL
24	2		*REAR BUMPER UPPER GROMMET LH/RH	25.00	0.00	*17.00 FL
25	4		*REVERSE SENSOR	25.00	0.00	*1,522.00 FL
26	4		*REVERSE SENSOR RING	25.00	0.00	*42.00 FL
27	1		*REAR BUMPER LOWER COVER	25.00	0.00	*380.50 FL
28	2		*REAR BUMPER SIDE COVER LH/RH	25.00	0.00	*221.00 FL
29	2		*REAR BUMPER REFLECTOR LH/RH	25.00	0.00	*159.20 FL
30	2		*REAR BUMPER REINFORCEMENT	25.00	0.00	*760.80 FL
31	1		*REAR END PANEL	25.00	0.00	*790.20 FL
32	1		*END PANEL TRIM	25.00	0.00	*360.50 FL
33	1		*REAR FLOOR PANEL	25.00	0.00	*1,347.50 FL
34	1		*LUGGAGE COMPARTMENT BOARD	25.00	0.00	*550.80 FL
35	1		*TOOL BOX SPONGE	25.00	0.00	*390.50 FL
36	1		*REAR FLOOR PANEL, UNDERNEATH COVER	25.00	0.00	*390.50 FL
37	2		*REAR FENDER LH/RH	25.00	0.00	*2,561.00 FL
38	2		*REAR FENDER TOP COVER LH/RH	25.00	0.00	*501.60 FL
39	2		*TAILLAMP PANEL LH/RH	25.00	0.00	*641.00 FL
40	1		*REAR FENDER INNER TRIM LH	25.00	0.00	*620.30 FL
41	10		*REAR FENDER INNER TRIM CLIPS LH	25.00	0.00	*55.00 FL
42	1		*REAR FENDER INNER TRIM RH	25.00	0.00	*618.30 FL
43	10		*REAR FENDER INNER TRIM CLIPS RH	25.00	0.00	*55.00 FL
44	1		*NUMBER PLATE	0	0.00	*40.00 FS
45	1		*BODY SEALING TAPE	0	0.00	*80.00 FS
46	1		*REAR WINDSCREEN SEALANT	0	0.00	*40.00 FS
47	1		*REAR WINDSCREEN PRIMER	0	0.00	*30.00 FS
Sub Total (\$\$)						20,888.90
- List Item Discount on L Items (\$\$)						5,174.73
Total Parts (\$\$)						15,714.17

F=Franchise part. S=SpcNett. L=ListItemDisc.

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO KNOCK, CUT, WELD REAR END PANEL, BOTH LH/RH REAR FENDER AND REAR BOOT FLOOR. TO REPLACE REAR DAMAGED PARTS AS RELATED TO ACCIDENT.	New	2,200.00
2	TO SPRAY PAINT ON REAR BOOT LID, REAR BUMPER, REAR END PANEL, REAR BOOT FLOOR, BOTH LH/RH REAR FENDER.	New	1,400.00
3	TO REMOVE AND REFIT REAR WINDSCREEN.	New	150.00
4	TO APPLY ANTI RUST PROOFING ON AFFECTED AREAS.	New	120.00
5	TO APPLY BODY SEALANT ON CUTTING AREAS.	New	120.00
6	TO TRANSFER/INSTALL TAILGATE LOCK MECHANISM, TAILGATE TRIM, WIRING HARNESS AND ATTACHED PARTS TO NEW UNITS.	New	120.00
7	TO REMOVE AND REFIT REAR SEAT, SEAT BELT, UPHOLSTERY, SIDE TRIM, ATTACHED PARTS TO ASSIST REPAIR.	New	120.00
8	TO INSTALL REVERSE SENSOR, CODING AND CHECK FUNCTIONING.	New	200.00
9	TO INSTALL REAR VIEW CAMERA AND SET UP IN HEADUNIT.	New	180.00
10	TO REMOVE AND REFIT EXHAUST SILENCER	New	200.00
11	TO DISMANTLE FUEL TANK TO ASSIST REPAIR.	New	200.00
12	TO DISCONNECT HYBRID BATTERY SYSTEM AND RESET SYSTEM.	New	400.00
13	TO CHECK FOR AND RECTIFY WIRING FAULT. TO CONDUCT DIAGNOSTIC CHECK AND FUNCTIONAL CHECK.	New	180.00
Gross Labour Cost (S\$)			5,590.00

Mova Automotive Pte Ltd/SMU467Y/28/12/2022 18:36. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >