

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/1159/2022/EQ
DATE : 27-Dec-22
WIP : 56172

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 29/12/2022

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS LIM ANN NA
ADDRESS : 3 ALEXANDRA VIEW
#42-08 ASCENTIA SKY
SINGAPORE 158749
TELEPHONE : HP +65 98398091
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1700063065-05
VEHICLE NO : **SFP 6009 G**
MODEL CODE : AUDI A5 SPORTBACK 2.0 TFS
MODEL YEAR : 10/10/2017
ENGINE NO : CVK 047200
CHASSIS NO : WAUZZZF5XJA034458
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 22-Dec-22
PLACE OF ACCIDENT : ON ALEXANDRA ROAD (BEFORE DAWSON ROAD)

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SFP 6009 G

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 800.00	X
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,400.00	1000
4	TO RESPRAY FRONT BUMPER AND BONNET.	\$ 2,500.00	1100
5	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 6,372.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFP 6009 G

					DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT		REMARKS	
1	FRONT BUMPER <i>Deformed</i>	1	\$	2,493.00	✓	
2	FRONT BUMPER FIXING PARTS <i>Not use</i>	1	\$	425.00	✗	
3	FRONT BUMPER SECURING STRIP - LH / RH <i>Not use</i>	2	\$	79.00	✗	
4	FRONT BUMPER GRILLE - CENTER <i>crushed</i>	1	\$	219.00	✓	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>Not use</i>	1	\$	254.00	✗	
6	FRONT BUMPER AIR GUIDE - LH / RH <i>Not use</i>	2	\$	144.00	✗	
7	RADIATOR GRILLE <i>crushed</i>	1	\$	2,576.00	✓	
8	FRONT PARKING AID SENSOR SUPPORT - LH / RH ?	2	\$	116.00	?	
9	RADIATOR GRILLE COVER - UPPER ?	1	\$	209.00	?	
10	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>Not use</i>	2	\$	1,058.00	✗	
11	FRONT BUMPER FOAM FILLER PIECE <i>Deformed</i>	1	\$	139.00	✓	
12	FRONT BUMPER REINFORCEMENT BEAM ?	1	\$	899.00	?	
13	FRONT BUMPER GUIDE SECTION - LH / RH <i>Not use</i>	2	\$	82.00	✗	
14	FRONT BUMPER TOP COVER ?	1	\$	143.00	?	
15	CAUTION SIGN STICKER ?	1	\$	16.00	?	
16	AIR CONDITIONER STICKER ?	1	\$	9.00	?	
17	LOCK CARRIER BRACKET <i>Not use</i>	1	\$	154.00	✗	
18	FRONT BUMPER SUPPORT - LH / RH ?	2	\$	64.00	?	
19	FRONT PARKING AID SENSOR - INNER / OUTER <i>Not use</i>	2	\$	531.00	✗	
20	FRONT PARKING AID SENSOR SEAL RING <i>Not use</i>	4	\$	10.00	✗	
SUB TOTAL SPARE PARTS		:	\$	9,620.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFP 6009 G

				DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	S/NETT	REMARKS
21	FRONT BUMPER WIRING SET	1	\$	567.00	X
22	HORN HIGH TONE - LH	1	\$	134.00	X
23	HORN LOW TONE - RH	1	\$	139.00	X
24	HORN BRACKET - LH / RH	2	\$	66.00	X
25	BONNET <i>Dented</i>	1	\$	3,491.00	✓
26	BONNET IMPACT PROTECTION - CENTER / LH / RH <i>new</i>	3	\$	93.00	✓
27	BONNET STRIKER - LH / RH <i>Not nee</i>	2	\$	112.00	X
28	BONNET LOCK - LH / RH <i>Not nee</i>	2	\$	455.00	+
29	BONNET BOWDEN CABLE - CENTER <i>Not nee</i>	1	\$	64.00	X
30	BONNET RELEASE LEVER	1	\$	15.00	+
31	HEADLIGHT - LH / RH	2	\$	16,832.00	+
32	LIFT CYLINDER - LH / RH	2	\$	434.00	X
33	LIFT CYLINDER BRACKET - LH / RH <i>new</i>	2	\$	34.00	+
34	LIFT CYLINDER CORRUGATED PIPE	1	\$	100.00	+
35	OUTSIDE TEMPERATURE SENSOR BRACKET	1	\$	21.00	?
36	RADIATOR AIR GUIDE - LH / RH INNER	2	\$	72.00	+
37	RADIATOR AIR GUIDE - LH / RH OUTER	2	\$	38.00	+
38	RADIATOR AIR GUIDE - LOWER / UPPER	2	\$	44.00	+
39	FRONT NO PLATE <i>Dented</i>	S/N	\$	60.00	✓
40	SUNDRIES		\$	400.00	?
TOTAL SPARE PARTS			:	\$ 32,791.00	
TOTAL LABOUR CHARGES			:	\$ 6,372.00	
GRAND TOTAL			:	\$ 39,163.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Ling*
SURVEYED DATE : *29/12/22*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 04 Days.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT