

(08/11/13) wof

ASS. REC. BY:

JASU

REF:

CS/EH122013002/Rwy3

9434

608-2026/Jan

ASSIGNMENT

From:

Date:

Estimated Cost:

OB / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

4P 30534

at Workshop m/s

SNA AH TEG

of

PIONEER RD NORTH

Insured:

EHI

Policy No.

Claims No.

Sum Insured:

Excess:

TB9

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

Bal. or Market Value:

145K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No.

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

REPAIR LHM II - 130K

Veh No:

4P 30534

Yr Regn:

2016 / Jan

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

VACUUM TANKER

Make:

ISUZU FVR34SU60C

c.c 7790

Colour

ORANGE

A/C: Insured / Std / NI / NA

Sp. Reading

487368

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JAL FVR34747600718

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

275/70R22.5

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

ANNAITE

Front

Rear

R/Bal.

8

mm

R/Bal.

8/8

mm

L/Bal.

8

mm

L/Bal.

8/8

mm

D.O.A.

22/12/22

D.O.I.

30/12/22

Survey held at

SNA AH TEG

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S FRT

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

) S + RS SI

☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Others

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

29/22, 4:50 PM

Estimate Report

Sng Ah Tee Motor & Panel Service Pte Ltd (Co.Reg.No:200810440N)

Blk 3 Pioneer Road North, #01-18

Singapore 628457

Tel: 6268 6183 Fax: 6268 1429 Email: sngahtee@singnet.com.sg; darren@sngahtee.com; janice@sngahtee.com

INSURER: **ERGO Insurance Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMCG22006968	Date of Loss:	22/12/2022
Vehicle Reg. No.:	YP3053Y	Driveable?	
Driver Age/Info:	39 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	QOOL ENVIRO PTE. LTD.	Contact No:	+6562654510
Driver:	SUBRAMANIAN PALANISAMY		

Make/Model:	ISUZU FVR34SUQDC, 7.8 D (M)	Vehicle Reg. Date:	15/06/2016
Vehicle Colour:	WHITE		
Engine No:	6HK1683379	Chassis No:	JALFVR347G7000718
Odometer:	487368 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	6

Description of Accident/Loss	REFER TO POLICE
Present Location:	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER)

COST OF CLAIMS

Parts	Amount
Miscellaneous Items	2,426.6
Labour	0.0
Paintwork Labour	1,330.0
Towing	0.0

Gross Total (\$\$)	3,756.6
+ GST 7.00% (\$\$)	262.9
Nett Amount (\$\$)	4,019.5

This claim is handled by: JANICE CHANG SIEW YIN

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 29 Dec 2022)
Parts:	N/A ISUZU FVR34SUQDC 7.8 D (M) (Model not available in database)
Labour:	Repairer's (Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YP3053Y)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT BUMPER <i>St</i>	0.00	0.00	*690.00 F
2	1		*FRT BUMPER OUTER GARNISH RH <i>scr</i>	0.00	0.00	*26.00 F
3	1		*FRT HEADLAMP RH <i>cm</i>	0.00	0.00	*335.00 F
4	1		*FRT HEADLAMP BRACKET RH <i>St</i>	0.00	0.00	*235.00 F
5	1		*FRT SIGNAL LAMP RH <i>cm</i>	0.00	0.00	*160.00 F
6	1		*FRT DOOR OUTER LOWER GARNISH RH <i>cm</i>	0.00	0.00	*145.00 F
7	1		*FRT DOOR LOWER SIDE SIGNAL LAMP RH <i>scr</i>	0.00	0.00	*40.00 F
8	1		*FRT UPPER STEP GARNISH RH <i>cm</i>	0.00	0.00	*130.00 F
9	1		*FRT LOWER STEP GARNISH RH <i>mis</i>	0.00	0.00	*55.00 F
10	1		*FRT LOWER STEP GARNISH SIDE HOLE COVER RH <i>mis</i>	0.00	0.00	*18.00 F
11	1		*FRT LOWER STEP ALLOY RH <i>mis</i>	0.00	0.00	*155.00 F
12	1		*FRT STEP PANEL BRACKET RH <i>St</i>	0.00	0.00	*205.00 F
13	1		*FRT DOOR LOWER SIGNAL LAMP BASE RH <i>cm</i>	0.00	0.00	*12.00 F

F=Franchise part.

Sub Total (\$\$)	2,206.00
+ Margin on L,N Items 10.00% (\$\$)	220.60
Total Parts (\$\$)	2,426.60

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO KNOCK FRT DOOR RH, FRT CORNER PANEL, WELD, REMOVE & REPLACE ABOVE PARTS	New	500 700.00
2	TO PUTTY & RESPRAY PAINTING ON AFFECTED AREA	New	500 600.00
3	TO CHECK WIRING	New	30.00
Gross Labour Cost (\$)			1,330.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rahul

H/ 90010068

5 days

L/S

30/12/22 @ 1400

EXCESS: TBA

Revised

Resy after repair

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	943H

Vehicle Details

Vehicle No.:	YP3053Y
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Dec 2022
Vehicle Make:	ISUZU
Vehicle Model:	FVR34SUQDC
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	6HK1683379
Chassis No.:	JALFVR347G7000718
Maximum Power Output:	-
Open Market Value:	\$65,173.00
Original Registration Date:	15 Jun 2016
First Registration Date:	15 Jun 2016
Transfer Count:	0
Actual ARF Paid:	\$3,259.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	14 Jun 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$43,002.00
COE Rebate Amount:	\$14,871.00
Total Rebate Amount:	\$14,871.00

The information contained herein is correct as at 23 Dec 2022

OK

Isuzu FVR34

Overview

[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)

Price	\$76,000	Lifespan ?	30-Oct-2034
Depreciation ?	\$41,650 /yr View models with similar depre	Reg Date	31-Oct-2014 (1yr 9mths 27days COE left)
Mileage	N.A.	Manufactured ?	2014
Road Tax ?	N.A.	Transmission	Manual
Dereg Value ?	\$1,786 as of today (change)	Fuel Type	Diesel
COE ?	\$9,786	OMV ?	\$52,542
Engine Cap	7,790 cc	ARF ?	\$2,628
Curb Weight ?	12,420 kg	No. of Owners ?	5
Type of Vehicle	Truck		