

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/HLA22013003/AQY3Q2**Date:** 24/02/2023REFERENCE

Handling Insurer:	HL Assurance Pte Ltd	Policy No:	MP314576
Claimant Vehicle No :	GZ9875M	Insured Vehicle No :	SLG8574D
Date of Loss:	28/12/2022	Nature of Claim:	TP
		Claim No:	MPC03937/RL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GZ9875M	Engine No:	1KD1526844
Make & Model:	TOYOTA PRIUS C CVT, 1.5 (A)	Chassis No:	JTFAT35Y103000090
Reg. Date:	19/12/2006 (Man. Year: 2006)	Odometer:	461751 km
Colour:	Blue		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	155 R12C
Front Left Side:	OHTSU 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	OHTSU 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,845.47	3,493.20	7,352.27	67.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,050.00	1,510.00	2,540.00	62.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,895.47	5,003.20	9,892.27	66.41
Approved Total (Overridden) (S\$)		4,000.00		
Nett Amount (S\$)	14,895.47	4,000.00	10,895.47	73.15

INSPECTION

Date of Assignment:	30/12/2022	JL PERFECT AUTOWORK PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875
Date Inspected:	30/12/2022 Inspected At:	
Estimated Period of Repair:	5.0 days	

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Feb 2023)
Parts:	144	TOYOTA PRIUS C CVT 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GZ9875M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*TAILGATE	Dented	1,370.00 FL	*1,370.00 FL
2	4	*TAILGATE HINGE	Bent (2 PCS ONLY)	660.00 FL	*330.00 FL
3	1	*TAILGATE SIDE LOCK	N/S Dented	250.00 FL	*125.00 FL
4	1	*TAILGATE STOPPER RUBBER	N/S Missing	70.00 FL	*35.00 FL
5	1	*TAILGATE STOPPER BRACKET	N/S Bent	350.00 FL	*175.00 FL
6	1	*TAILGATE STICKER TOYOTA	Necessary	167.60 FL	*167.60 FL
7	1	*NUMBER PLATE BRACKET	Bent	186.00 FL	*186.00 FL
8	2	*SIDE GATE SAFETY LOCK	Not Necessary	264.20 FL	*- FL
9	1	*TAIL LAMP	N/S Cracked	490.00 FL	*245.00 FL
10	1	*TAIL LAMP SUPPORT BRACKET	N/S Bent	370.00 FL	*185.00 FL
11	1	*REAR STICKER DYNA	Necessary	45.00 FL	*45.00 FL
12	1	*REAR END PANEL	Dented	1,245.00 FL	*495.00 FL
13	1	*SPARE TYRE CHAIN BOX	Damaged	295.00 FL	*295.00 FL
14	1	*REAR CHASSIS CROSSMEMBER	Bent	2,364.50 FL	*924.00 FL
15	1	*REAR NUMBER PLATE	Bent	50.00 FS	*30.00 FS
16	1	*TAIL GATE ALUMINIUM COVER (SPECIAL TYPE)	Not Necessary	680.00 FS	*- FS
17	1	*TAIL GATE 70KM/H STICKER	Necessary	40.00 FS	*15.00 FS
18	1	*TAIL GATE STICKER 6 PAX	Necessary	40.00 FS	*15.00 FS
19	2	*SIDE GATE COMPANY STICKER (SPECIAL TYPE)	Not Necessary	760.00 FS	*- FS
20	1	*REAR END PANEL SEALANT	Not Necessary	150.00 FS	*- FS
21	1	*REAR FLOOR TOP ALUMINIUM PANEL (SPECIAL TYPE)	Not Necessary	2,500.00 FS	*- FS
22	1	*SARE TYRE (BIG)	Not Necessary	350.00 FS	*- FS
23	1	*SARE TYRE (SMALL)	Not Necessary	180.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	12,877.30	4,637.60
- List Item Discount on L Items 25.00/25.00% (\$)	2,031.83	1,144.40

Total Parts (S\$) 10,845.47 3,493.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT ,WELD ,CUT ,ADJUST KNOCK	New	1,800.00	700.00
2	TO PUTTY ,SPRAY PAINT ,POLISH WAX	New	1,200.00	700.00
3	TO APPLY TUFF COAT	New	350.00	80.00
4	REMOVE AND REFIX REAR CARGO BED	New	600.00	0.00
5	WIRING	New	100.00	30.00
Gross Labour Cost (S\$)			4,050.00	1,510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >