

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



DATE : 29.12.2022

JTFAT357103000090
Xiao Chan.

TO : HL MOTOR CLAIMS DEPTS
VEHICLE NO : GZ9875M
MODEL : TOYOTA DYNA
DATE OF ACCIDENT : 28.12.2022
TIME OF ACCIDENT : 16:30 HRS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE Dented.	1	\$ 1,370.00	\$ 1,370.00
2	TAILGATE HINGE 2 pieces Bent	4	\$ 165.00	\$ 660.00
3	TAILGATE SIDE LOCK LH Dented	2	\$ 125.00	\$ 250.00
4	TAILGATE STOPPER RUBBER LH Missing	2	\$ 35.00	\$ 70.00
5	TAILGATE STOPPER BRACKET LH Bent	2	\$ 175.00	\$ 350.00
6	TAILGATE STICKER 'TOYOTA' New	1	\$ 167.60	\$ 167.60
7	NUMBER PLATE BRACKET Bent	1	\$ 186.00	\$ 186.00
8	SIDE GATE SAFETY LOCK New	2	\$ 132.10	\$ 264.20
9	TAIL LAMP LH Cracked	2	\$ 245.00	\$ 490.00
10	TAIL LAMP SUPPORT BRACKET LH Bent	2	\$ 185.00	\$ 370.00
11	REAR STICKER 'DYNA' New	1	\$ 45.00	\$ 45.00
12	REAR END PANEL Dented	1	\$ 1,245.00	\$ 1,245.00
13	SPARE TYRE CHAIN BOX Dented	1	\$ 295.00	\$ 295.00
14	REAR CHASSIS CROSSMEMBER Repair Bent	1	\$ 2,364.50	\$ 2,364.50

4577.60
3433.20

TOTAL PRICE \$ 8,127.30
LESS 25% \$ 2,031.83
SUB TOTAL PRICE \$ 6,095.48

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE Bent	1	\$ 50.00	\$ 50.00
2	TAIL GATE ALUMINIUM COVER (SPECIAL TYPE) New	1	\$ 680.00	\$ 680.00
3	TAIL GATE '70KM/H' STICKER New	1	\$ 40.00	\$ 40.00

TO : HL MOTOR CLAIMS DEPTS
 VEHICLE NO : GZ9875M
 MODEL : TOYOTA DYNA
 DATE OF ACCIDENT : 28.12.2022
 TIME OF ACCIDENT : 16:30 HRS

4	TAIL GATE STICKER '6 PAX' <i>new</i>	1	\$ 40.00	\$ 40.00 <i>15</i>
5	SIDE GATE COMPANY STICKER (SPECIAL TYPE) <i>HL</i>	2	\$ 380.00	\$ 760.00 <i>+</i>
6	REAR END PANEL SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00 <i>+</i>
7	REAR FLOOR TOP ALUMINIUM PANEL (SPECIAL TYPE) <i>HL</i>	1	\$ 2,500.00	\$ 2,500.00 <i>+</i>
8	SPARE TYRE (BIG) <i>HL</i>	1	\$ 350.00	\$ 350.00 <i>+</i>
9	SPARE TYPE (SMALL) <i>HL</i>	1	\$ 180.00	\$ 180.00 <i>+</i>
TOTAL			\$ 4,750.00	

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, WELD, CUT, ADJUST, KNOCK	\$ 1,800.00	<i>700</i>
2	TO PUTTY, SPRAY PAINT, POLISH WAX	\$ 1,200.00	<i>700</i>
3	<i>To apply tuff coat;</i>	\$ 350.00	<i>X 80.</i>
5	REMOVE AND REFIX REAR CARGO BED	\$ 600.00	<i>X</i>
6	<i>Wiring</i>	\$ 100	<i>X 30</i>
TOTAL		\$ 4,600.00	

ESTIMATE REPORT

TOTAL PARTS COST : \$ 10,845.48
 TOTAL LABOUR COST : \$ 4,600.00
 TOTAL REPAIR COST : \$ 15,445.48

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP : 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

for:

Adrian
2/s 30/12/22
05 Days
total: 500320

L/s: AK

AK