

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG122013026/RNY3Q2**Date:** 06/07/2023**REFERENCE**

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:

Claimant Vehicle No : SLC7011P **Insured Vehicle No :** XE2000B

Date of Loss: 29/12/2022 Nature of Claim: TP Claim No: CDMCG22002811-001

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLC7011P**

Make & Model: TOYOTA VIOS, 1.5 (A) Engine No: 1NZZ327665

Reg. Date: 24/05/2016 (Man. Year: 2015) Chassis No: MHFBT9F3706065564

Colour: Grey Odometer: 73839 km

Engine Capacity: 1497 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/50 R16 Rear Tyre Size: 205/50 R16

Front Left Side: West Lake 6 mm Rear Left Side: West Lake 6 mm

Front Right Side: West Lake 6 mm Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,460.00	2,542.87	3,917.13	60.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,535.00	1,935.00	600.00	23.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,995.00	4,477.87	4,517.13	50.22
Approved Total (Overridden) (S\$)		3,550.00		
(S\$)	8,995.00	3,550.00	5,445.00	60.53
+ GST 8.00/8.00% (S\$)	719.60	284.00	435.60	60.53
Nett Amount (S\$)	9,714.60	3,834.00	5,880.60	60.53

INSPECTION

Date of Assignment: 30/12/2022

Date Inspected: 06/01/2023 Inspected At: Automotive Repair Centre Pte Ltd (Toh Guan Road East)
48 TOH GUAN ROAD EAST ENTERPRISE HUB,
#02-146/167
Singapore 608586

Estimated Period of Repair: 8.0 days

Adjuster: MOHD RASUL**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Jul 2023)
Parts:	143	TOYOTA VIOS 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLC7011P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	450.00 F	*- FL
2	1		*REAR WINDSCREEN MOULDING	Necessary	150.00 F	*100.00 FL
3	1		*REAR FENDER RH	Buckled	1,050.00 F	*1,050.00 FL
4	1		*REAR FENDER SHIELD RH	Not Necessary	150.00 F	*- FL
5	1		*REAR DOOR RH	Bent	900.00 F	*900.00 FL
6	1		*REAR DOOR GARNISH RH	Not Necessary	210.00 F	*- FL
7	1		*REAR DOOR UPPER HINGE RH	Not Necessary	110.00 F	*- FL
8	1		*REAR DOOR LOWER HINGE RH	Not Necessary	110.00 F	*- FL
9	1		*REAR DOOR WEATHERSTRIP RH	Necessary	260.00 F	*215.00 FL
10	1		*REAR DOOR BLACK OUT TAPE RH	Necessary	80.00 F	*72.00 FL
11	1		*FRONT DOOR RH	Bent	900.00 F	*673.16 FL
12	1		*FRONT DOOR GARNISH RH	Not Necessary	210.00 F	*- FL
13	1		*FRONT DOOR UPPER HINGE RH	Not Necessary	110.00 F	*- FL
14	1		*FRONT DOOR LOWER HINGE RH	Not Necessary	110.00 F	*- FL
15	1		*FRONT DOOR WEATHERSTRIP RH	Necessary	260.00 F	*215.00 FL
16	1		*FRONT DOOR BLACK OUT TAPE RH	Necessary	80.00 F	*72.00 FL
17	1		*SIDE MIRROR ASSY RH	Repair	650.00 F	*- FL
18	1		*SIDE SILL PANEL RH	Repair	600.00 F	*- FL
19	10		*REAR FENDER SHIELD CLIPS	Necessary	30.00 FS	*30.00 FS
20	1		*REAR WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	6,460.00	3,367.16
- List Item Discount on L Items 0.00/25.00% (S\$)	0.00	824.29
Total Parts (S\$)	6,460.00	2,542.87

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINT (REAR BUMPER ,REAR DOOR RH ,FRONT DOOR RH ,REAR FENDER RH ,SIDE MIRROR RH ,SIDE SILL RH INCLUDE BLENDING)	New	1,200.00	900.00
2	REMOVE ,REPLACE AND REFIT ACCIDENT AFFECTED PARTS	New	1,200.00	900.00
3	REMOVE & REFIT REAR WINDSCREEN TO FACILITATE REPAIR	New	100.00	100.00
4	CHECK AND RECTIFY ELECTRICAL WIRING	New	35.00	35.00
Gross Labour Cost (\$\$)			2,535.00	1,935.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >