

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: ERGO Insurance Pte. Ltd.
8 Temasek Boulevard
#04-01 Suntec Tower Three
Singapore 038988

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 27 Jun 2023

Preliminary Advice

Insured Vehicle No	: XE2000B	Accident Date	: 29/12/2022
TP Vehicle No	: SLC7011P	Assignment Date	: 30/12/2022
Make	: TOYOTA VIOS	Est. Duration of Repair	: 8
Date of Inspection	: 06/01/2023		
Inspection At	: AUTOMOTIVE REPAIR CENTRE PTE LTD (TOH GUAN ROAD EAST) 48 TOH GUAN ROAD EAST ENTERPRISE HUB, #02-146/167 SINGAPORE 608586		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,995.00
Revised Amount	:S\$	5,685.00
Check Items (Estimated)	:S\$	150.00
Total	:S\$	5,835.00

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments :Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.