

48 Toh Guan Road East (Enterprise Hub)
#02-146, Singapore 608586
Tel: 64688834 Fax: 67228585
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2212-700-TG
DATE : 29-Dec-2022
POLICY NO. :
VEHICLE REG. NO. : SLC7011P
VEHICLE MAKE : TOYOTA / VIOS E GRADE 2015
MHFBT9F3706065564

TO Motor Claim Department
ERGO Insurance Pte Ltd
8 Temasek Boulevard, #04-01
Suntec Tower Three, (S)038988
Tel: 68299199

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
SPARE PARTS				
1	Rear Bumper <i>repair</i>	1	\$ 450.00	\$ 450.00
2	Rear Windscreen Moulding <i>m</i>	1	\$ 150.00	\$ 150.00
3	Rear Fender RH <i>bu</i>	1	\$ 1,050.00	\$ 1,050.00
4	Rear Fender Shield RH <i>?</i>	1	\$ 150.00	\$ 150.00
5	Rear Door RH <i>bt</i>	1	\$ 900.00	\$ 900.00
6	Rear Door Garnish RH <i>X</i>	1	\$ 210.00	\$ 210.00
7	Rear Door Upper Hinge RH <i>X</i>	1	\$ 110.00	\$ 110.00
8	Rear Door Lower Hinge RH <i>X</i>	1	\$ 110.00	\$ 110.00
9	Rear Door Weatherstrip RH <i>m</i>	1	\$ 260.00	\$ 260.00
10	Rear Door Black Out Tape RH <i>m</i>	1	\$ 80.00	\$ 80.00
11	Front Door RH <i>bt</i>	1	\$ 900.00	\$ 900.00
12	Front Door Garnish RH <i>X</i>	1	\$ 210.00	\$ 210.00
13	Front Door Upper Hinge RH <i>X</i>	1	\$ 110.00	\$ 110.00
14	Front Door Lower Hinge RH <i>X</i>	1	\$ 110.00	\$ 110.00
15	Front Door Weatherstrip RH <i>m</i>	1	\$ 260.00	\$ 260.00
16	Front Door Black Out Tape RH <i>m</i>	1	\$ 80.00	\$ 80.00
17	Side Mirror Assy RH <i>repair</i>	1	\$ 650.00	\$ 650.00
18	Side Sill Panel RH <i>repair</i>	1	\$ 600.00	\$ 600.00
Total Spare Parts				\$ 6,390.00
SPECIAL NETT				
19	Rear Fender Shield Clips <i>m</i>	10	\$ 3.00	\$ 30.00
20	Rear Windscreen Sealant <i>m</i>	1	\$ 40.00	\$ 40.00
Total Special Nett				\$ 70.00

48 Toh Guan Road East (Enterprise Hub)
#02-146, Singapore 608586
Tel: 64688834 Fax: 67228585
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2212-700-TG
DATE : 29-Dec-2022
POLICY NO. :
VEHICLE REG. NO. : SLC7011P
VEHICLE MAKE : TOYOTA / VIOS E GRADE 2015
MHFBT9F3706065564

TO Motor Claim Department
ERGO Insurance Pte Ltd
8 Temasek Boulevard, #04-01
Suntec Tower Three, (S)038988
Tel: 68299199

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	<u>LABOUR</u>			
21	Spray Paint (Rear Bumper, Rear Door RH, Front Door RH, Rear Fender RH, Side Mirror RH, Side Sill RH Include Blending)	1	\$ 1,200.00	\$ 1,200.00 900
22	Remove, Replace and Refit Accident Affected Parts	1	\$ 1,000.00	\$ 1,200.00 900
23	Remove & Refit Rear Windscreen To Facilitate Repair	1	\$ 100.00	\$ 100.00
24	Check and Rectify Electrical Wiring	1	\$ 35.00	\$ 35.00
Total Labour				\$ 2,535.00
Amount Before Excess				\$ 8,995.00
Add GST @ 7%				629.65
Total Amount Payable				\$ 9,624.65

Estimate prepared by: RAZALI

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed.

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Razali
Hp 900100 68
8 days
L/S
06/01/23 @1030
Res after repair