

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : LIBERTY INSURANCE PTE LTD
51 CLUB STREET
#03-00 LIBERTY HOUSE
SINGAPORE 069428
TEL: 62218611 FAX: 62241047
ATTN: Motor Claim Department

VECON

Estimate No: EST2200421
Date: 28 Dec 2022

Veh Reg No: SGY1089Z
Make/Model: MITSUBISHI LANCER
1.6 M
Chasis No: JMYSNCS3A7U010044
Reg. Date: 17/09/2007
Your Ref No: SNE2577Y

Claim Type: Third Party
Accident Date: 27/12/2022
TP Veh Reg No: SNE2577Y

Estimate Repair Cost to Vehicle No :SGY1089Z

Quantity	Description	List Price	Amount
		SS	SS
List Price			
1	1 PC REAR BUMPER Distorted	655.00	✓
2	1 PC REAR BUMPER REINFORCEMENT Bent	171.00	✓
3	1 PC REAR BUMPER SIDE RETAINER LH Bent Rmd	58.00	✓
4	1 PC REAR PANEL Dented	406.00	✓
5	1 PC REAR PANEL Top Garnish Damaged	145.00	✓
6	1 PC BOOT LID New	545.00	+
7	1 PC BOOT LID RUBBER	164.00	+
8	1 PC BOOTLID "GLX" EMBLEM } New	38.00	+
9	1 PC BOOTLID LOGO EMBLEM	45.00	+
10	1 PC BOOTLID "LANCER" EMBLEM New	36.00	+
11	1 PC REAR FENDER LH Rys	788.70	+
12	1 PC REAR FENDER INNER TRIM LH New	122.00	+
13	1 PC TAIL LAMP LH Combed	397.00	344
		3,570.70	
Less 10%		357.07	3,213.63
Special Net			
14	1 SET REVERSE SENSORS Rmd	250.00	200
15	1 PC REAR WINDSCREEN SEALANT } New	60.00	+
16	1 PC REAR WINDSCREEN INNER SEAL RUBBER	60.00	
		370.00	370.00
Labour			
17	1 TO CHECK WIRING	50.00	30
18	1 TO REMOVE AND REFIT CUSHION & INNER TRIM	180.00	50
19	1 TO REMOVE AND REFIT REAR WINDSCREEN	120.00	+
20	1 TO REMOVE AND REFIT PETROL TANK	150.00	+
21	1 TO SPRAY PANEL SEALANT	100.00	60
22	1 (REAR) TO SPRAY PAINTING	1,200.00	700

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : LIBERTY INSURANCE PTE LTD
51 CLUB STREET
#03-00 LIBERTY HOUSE
SINGAPORE 069428

TEL: 62218611 FAX: 62241047
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 27/12/2022
TP Veh Reg No: SNE2577Y

Estimate No: EST2200421

Date: 28 Dec 2022

Veh Reg No: SGY1089Z
Make/Model: MITSUBISHI LANCER
1.6 M

Chasis No: JMYSNCS3A7U010044

Reg. Date: 17/09/2007

Your Ref No: SNE2577Y

Estimate Repair Cost to Vehicle No :SGY1089Z

Quantity	Description	List Price	Amount
		SS	SS
23	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,200.00	600
		3,000.00	3,000.00
		Total	S\$ 6,583.63
		Add GST @ 7%	460.85
		Total Amount Payable	S\$ 7,044.48

TOTAL: SINGAPORE DOLLAR SEVEN THOUSAND FORTY FOUR AND CENTS FORTY EIGHT ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian L
A/S 30/12/22

OS Png

Total: 3241.10
A/S: 2.6k

2.6k