

ASS. REC. BY:

REF:

122013029/kv

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Thian 14/1

of _____

Insured: SLN 7300Y

Policy No. _____


Claims No. AVS23/0054

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: \$7500

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 08 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: 08/23 Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLA 2128E Yr Regn: 06, 08

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or MPVMake: Toy Wish c.c. 1794Colour: m. Silver A/C: Insured / Std / NI / NASp. Reading: 436878 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: BNE10 0408110Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt or

Mod: NII / S/Rim / STD A/Rim or

Tyre Size: F: Sumi 1P5/65R15R: CSTBS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front _____ Rear _____

R/Bal. 7 mm R/Bal. 8 mmL/Bal. 7 mm L/Bal. 8 mmD.O.A. 24/12/22 D.O.I. 29/12/2022

Survey held at _____

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

cls body & u/c

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 GIA & EN not ready10/3 115m @ 5500k Carbur (red 14,044.90, 71%)

Date/Time, File Pass to?

☐ : Prell. Report☐ : Final ReportDays Of Repair: 8Resurvey No. of Trip: 1

Survey Fee:

Transportation

S + RS. \$

Fees

Others

TOTAL

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Date/Time, File Return to?

1) _____
2) 17/3-23-typistReport Format: TPLump Sum / L.B.I: (\$ 5500)

Repair Estimate

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721


Mobile: 82636295 Email: thiamhenghuat@gmail.com

Make/Model: TOYOTA WISH
Engine/Chassis No.: ZNE100408110
Date of accident: 27.12.22
Damaged area: O/S

Date: 06/01/2023

Claim Type: TP

VRN: SLA2128E



List items				
S/N	Parts description	QTY	UNIT PRICE	AMOUNT
1	Front door o/s	1	\$ 925.00	\$ 925.00
2	Front door upper hinge o/s	1	\$ 62.00	\$ 62.00
3	Front door lower hinge o/s	1	\$ 62.00	\$ 62.00
4	Front door weatherstrip o/s	1	\$ 185.00	\$ 185.00
5	Front door inner lock o/s	1	\$ 346.00	\$ 346.00
6	Front door inner trim board o/s	1	\$ 572.00	\$ 572.00
7	Front door outer handle o/s	1	\$ 213.00	\$ 213.00
8	Front door lock cylinder o/s	1	\$ 134.00	\$ 134.00
9	Front door window channel o/s	1	\$ 104.00	\$ 104.00
10	Front door window channel moulding o/s	1	\$ 65.00	\$ 65.00
11	Front door window regulator o/s	1	\$ 269.00	\$ 269.00
12	Front door window regulator motor o/s	1	\$ 383.00	\$ 383.00
13	Front door stopper o/s	4	\$ 7.90	\$ 31.60
14	Front door lock striker o/s	1	\$ 65.00	\$ 65.00
15	Front door checker o/s	1	\$ 59.00	\$ 59.00
16	Rear door o/s	1	\$ 828.00	\$ 828.00
17	Rear door upper hinge o/s	1	\$ 62.00	\$ 62.00
18	Rear door lower hinge o/s	1	\$ 62.00	\$ 62.00
19	Rear door weatherstrip o/s	1	\$ 185.00	\$ 185.00
20	Rear door inner lock o/s	1	\$ 316.00	\$ 316.00
21	Rear door inner trim board o/s	1	\$ 572.00	\$ 572.00
22	Rear door outer handle o/s	1	\$ 253.00	\$ 253.00
23	Rear door window channel o/s	1	\$ 104.00	\$ 104.00
24	Rear door window channel moulding o/s	1	\$ 65.00	\$ 65.00
25	Rear door window regulator o/s	1	\$ 269.00	\$ 269.00
26	Rear door window regulator motor o/s	1	\$ 383.00	\$ 383.00
27	Rear door stopper o/s	4	\$ 7.90	\$ 31.60
28	Rear door lock striker o/s	1	\$ 43.00	\$ 43.00
29	Rear door checker o/s	1	\$ 59.00	\$ 59.00
30	Front fender o/s	1	\$ 764.00	\$ 764.00

Repair Estimate

31	Front fender cowling o/s	Fr	1	\$ 187.00	\$ 187.00	✓
32	Front shock absorber o/s	Rt	1	\$ 485.00	\$ 485.00	✓
33	Front shock absorber top mounting o/s	Rt	1	\$ 98.00	\$ 98.00	✓
34	Front shock absorber top bearing o/s	Rt	1	\$ 62.00	\$ 62.00	✓
35	Front knuckle arm o/s	Rt	1	\$ 389.00	\$ 389.00	✓
36	Front knuckle bearing o/s	Rt	1	\$ 187.00	\$ 187.00	✓
37	Front lower arm o/s	Rt	1	\$ 379.00	\$ 379.00	✓
38	Anti roll bar endlink o/s	Rt	1	\$ 145.00	\$ 145.00	✓
39	Rear fender o/s	R	1	\$ 702.00	\$ 702.00	X
40	Rear fender cowling o/s	R	1	\$ 185.00	\$ 185.00	X
41	Rear fender splash guard o/s	R	1	\$ 76.00	\$ 76.00	X
42	Rear bumper	Bm	1	\$ 676.00	\$ 676.00	✓
43	Rear bumper retainer	Rt	2	\$ 85.00	\$ 170.00	4
44	Rear axle	R	1	\$ 1,321.00	\$ 1,321.00	X
45	Rear shock absorber o/s	R	1	\$ 355.00	\$ 355.00	X
46	Rear shock absorber top mount o/s	R	1	\$ 53.00	\$ 53.00	X
47	Rear spring o/s	R	1	\$ 165.00	\$ 165.00	X
48	Rear wheel hub o/s	R	1	\$ 366.00	\$ 366.00	X
49	Rocker panel skirting o/s	R	1	\$ 515.00	\$ 515.00	X
50	Rocker panel o/s	R	1	\$ 623.00	\$ 623.00	X
51	Wing mirror assy o/s	NN	1	\$ 451.00	\$ 451.00	X
52	Front fender inner panel o/s	Rt	1	\$ 693.00	\$ 693.00	✓
53	Front fender signal lamp o/s	Rt	1	\$ 125.00	\$ 125.00	✓
54	Front bumper	Rt	1	\$ 695.00	\$ 695.00	✓
55	Front bumper side retainer	CM	2	\$ 53.00	\$ 106.00	✓
56	Front bumper inner sponge	R	1	\$ 138.00	\$ 138.00	X
57	Headlamp o/s	Rt	1	\$ 950.00	\$ 950.00	✓
58	Headlamp top panel o/s	Rt	1	\$ 160.00	\$ 160.00	✓
				Subtotal	\$ 17,929.20	
				List discount	25.00%	
				Total	\$ 13,446.90	

Special nett items					
No.	Parts description		QTY	UNIT PRICE	AMOUNT
1	Front door inner trim board clips o/s	NN	8	\$ 5.50	\$ 44.00
2	Rear door inner trim board clips o/s	NN	8	\$ 5.50	\$ 44.00
3	Front fender cowling clips o/s	NN	8	\$ 5.50	\$ 44.00
4	Rear fender cowling clips o/s	NN	8	\$ 5.50	\$ 44.00
5	Front & Rear bumper clips	NN	24	\$ 5.50	\$ 132.00
6	Rocker panel sealant o/s	NN	1	\$ 80.00	\$ 80.00
7	Front alloy wheel o/s	Rd	1	\$ 450.00	\$ 450.00
8	Rear alloy wheel o/s	Rd	1	\$ 450.00	\$ 450.00
9	Front tyre o/s	Rd	1	\$ 280.00	\$ 280.00
10	Rear tyre o/s	Rd	1	\$ 280.00	\$ 280.00
11	Sundries	NN	1	\$ 50.00	\$ 50.00
Total					\$ 1,898.00

Repair Estimate

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew the accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	9	\$ 1,800.00
2	To disconnect both o/s doors wire harness and electrical component to facilitate repairs, reconnect and check functions of power windows.	0.5	\$ 100.00
3	To rust proof all affected portions after repair.	0.5	\$ 100.00
4	To remove and refit both o/s tyres & rims for replacement. To perform tyre balancing.	0.5	\$ 100.00
5	To remove and refit o/s front & rear undercarriage for replacement of parts.	2	\$ 400.00
6	To conduct computerized 4 wheel alignment.	0.5	\$ 100.00
7	Supply spray paint material and necessary items to respray affected area / panel.	8	\$ 1,600.00
Total labour			\$ 4,200.00

Estimate Grand Total	\$ 19,544.90
----------------------	--------------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1100/-
✓
✓
20/-
200/-
60/-
1400/-