

EM Solution Pte Ltd

160 Sin Ming Drive #03-18/19, Sin Ming Autocity
Singapore 575722
Tel: 64560226 Fax: 64584500
GST Reg. No: 201016308K

Not Notified
11 Day @ 3050h
Putty After Paint
4 days

ESTIMATE

Date : 31st Dec 2022

Mr Oke Chee Hau
120 Lorong L, Telok Kurau #04-01
Singapore 425553

Veh No : SNB 538P
Make/Model : Toyota Noah
Chassis No : ZWF800352177
Date of Acc : 29.12.22
TP Veh No : SDA 3828G

S/No	Qty	Description	Unit Price	Amount
Materials				
1	1 pc	Frt Door RH <i>1672.30</i>		
2	1 pc	Frt Door Sticker <i>84.50</i>		
3	1 pc	Rear Door RH <i>1594</i>		
4	1 pc	Rear Door Sticker		
5	1 pc	Rocker Panel RH		
				<i>By</i> \$ 2,007.90
				<i>m</i> \$ 217.50
				<i>m</i> \$ 2,183.10
				<i>m</i> \$ 98.10
				<i>r</i> \$ 827.10
				\$ 5,333.70
			Less 25% :	\$ 1,333.43
			Parts Total :	\$ 4,000.28
Labour				
1		To remove & rearrange electrical wirings, check lightings		
2		To remove, transfer frt & rear doors components		
3		To remove, repair & replace damaged bodyparts, realign bodywork and where consistent to the accident.		
4		Putty and respray painting on affected portions.		
5		Rust proofing on affected portions.		
				\$ 100.00
				\$ 200.00
				\$ 600.00
				\$ 800.00
				\$ 100.00
			Labour Total :	\$ 1,800.00
			Total Parts & Labour :	\$ 5,800.28

Qin
for EM Solution Pte Ltd

Note: Parts quoted were based on visual inspection. Should additional parts be found damaged upon dismantling, we will seek your approval before proceeding.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company