

ASS. REC. BY:

REF:

CS/EQI 22013036/Dm³

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: **SFD 1348Z**

Policy No. _____


Claims No. **DM22HO02286**

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: **5.8** days Res.: Yes or NoLum Sum: **7/P** % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **SNB 45807** Yr Regn: **June 2017**Type: **M.Car** / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **Hyundai Tucson** c.c. **1591**Colour: **Red** A/C: Insured / Std / NI / NASp. Reading: **67173** T/Radio: Insured / Std / NI / NAEng/No: **G4FJHU493815**C/No: **KM1J338122VJU490514**Gen. Cond: **Good** / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: **225/60 R17**R: **— " —**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Pirelli

Front

Rear

R/Bal. **S** mm R/Bal. **S** mmL/Bal. **S** mm L/Bal. **S** mmD.O.A. **29/12/2022** D.O.I. **30/12/2022**Survey held at **Atyred Auto**

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

H/S Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

EQI SFD 1348Z**20/01/23****know PIP 3,876.56 with 5 days of work (red 13,996.04, 78%)**

Date/Time, File Pass to?



: Prel. Report

Days Of Repair: **5**

1)



: Final Report

Resurvey No. of Trip: **2**

Date/Time, File Return to?

2) **20/1/23-typist**

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Insp (\$

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

Report Form: **TP**Report Form: **\$3876.56**

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	840K

Vehicle Details

Vehicle No.:	SNB4580P
Vehicle to be Exported:	Yes
Intended Deregistration Date:	20 Jan 2023
Vehicle Make:	HYUNDAI
Vehicle Model:	TL TUCSON 1.6 GLS T-GDI DCT 2WD
Primary Colour:	Red
Manufacturing Year:	2017
Engine No.:	G4FJHU493815
Chassis No.:	KMHJ3812VJU490514
Maximum Power Output:	130.0 kW (174 bhp)
Open Market Value:	\$19,961.00
Original Registration Date:	24 Jun 2017
First Registration Date:	24 Jun 2017
Transfer Count:	1
Actual ARF Paid:	\$19,961.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Jun 2027
PARF Rebate Amount:	\$13,972.00

Intended COE Rebate Details

COE Expiry Date:	23 Jun 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$47,501.00
COE Rebate Amount:	\$21,019.00
Total Rebate Amount:	\$34,991.00

The information contained herein is correct as at 20 Jan 2023

OK




ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
Email: alfredauto@hotmail.com

Tyre &
Sports Rim



Reference: 291222

[WITHOUT PREJUDICE **SAVE AS TO COSTS**]

Date: 29.12.2022

Aik Chin Hin Pte Ltd

Blk 5022 Ang Mo Kio Industrial Park 2

Singapore 569525.

Hyundai Tucson

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimate Repair Cost for Motor Vehicle Reg. No: SNB 4580 P

1 Pc. Front LH Door <i>fine</i>		1,531.00	✓
2 Pcs. Front LH Door Hinger <i>mm</i>	@ 155.00	310.00	X
1 Pc. Front LH Door Stopper <i>mm</i>		69.00	X
1 Pc. Front LH Door Moudling <i>mm</i>		98.80	X
1 Pc. Front LH Door Outer Handle Assy. <i>mm</i>		391.00	X
1 Pc. Front LH Door Lock <i>mm</i>		288.00	X
1 Set. Front LH Door Channel Sticker (3pcs) <i>mm</i>		210.00	✓ 80/- SN
1 Pc. Front LH Door Protector <i>cut</i>		198.00	✓
10 Pcs. Front LH Door Protector Clips <i>mm</i>	@ 6.00	60.00	15/- SN
1 Pc. Front LH Door Inner Seal <i>mm</i>		128.00	X
1 Pc. Front LH Door Weather Slip <i>mm</i>		399.00	✓ 189.20
1 Pc. Front LH Door Frame Rubber <i>mm</i>		425.00	X
1 Pc. Rear LH Door <i>mm</i>		1,513.00	✓ 1208.00
2 Pcs. Rear LH Door Hinger <i>mm</i>	@ 155.00	310.00	X
1 Pc. Rear LH Door Stopper <i>mm</i>		69.00	X
1 Pc. Rear LH Door Moudling <i>mm</i>		98.80	X
1 Pc. Rear LH Door Outer Handle <i>mm</i>		368.00	X
1 Pc. Rear LH Door Lock <i>mm</i>		275.00	X
1 Set. Rear LH Door Channel Sticker (3pcs) <i>mm</i>		210.00	✓ 80/- SN
1 Pc. Rear LH Door Protector <i>cut</i>		238.00	✓
10 Pcs. Rear LH Door Protector Clips <i>mm</i>	@ 6.00	60.00	15/- SN
1 Pc. Rear LH Door Inner Seal <i>mm</i>		128.00	X
1 Pc. Rear LH Door Weather Slip <i>mm</i>		389.00	✓ 169.00
1 Pc. Rear LH Door Frame Rubber <i>mm</i>		440.00	X
1 Pc. Rear LH Corner Sticker <i>mm</i>		128.00	X
1 Pc. Centre Door Frame Pillar <i>mm</i>		3,028.00	X
1 Pc. LH Step Panel <i>mm</i>		1,130.00	X
2 Pcs. LH Step Panel Chrome <i>mm</i>	@ 195.00	390.00	X
2 Pcs. Door Seal Sealant <i>mm</i>	@ 60.00	120.00	X

SH 190.00

List 3533.20

2020 2826.56

Total (Panels / Parts):

13,002.60 (SGD)



ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4585 Fax: 6483 4882 Reg. No. 391089/00-E
Email: alfredauto@hotmail.com

Tyre &
Sports Rim



LABOR CHARGES

To remove & refit door wiring & check all affected wire.	360.00 120/-
To remove & refit interior garnish cushion & cover.	300.00 H4
To remove & refit door glass.	250.00 H4
To welding, knocking, straightening repair & renew all Accident affected area.	1,800.00 200/-
To respray painting on inner & outer portion & all accident Affected area.	1,800.00 500/- 860.00
To rust proof all accident affected area.	160.00 40/-
To reseal front & rear door inner seal.	200.00 H4

Total (Labor Charges): 4,870.00 (SGD)

7/P 3876.56

TOTAL COST SUMMARY

PANELS / PARTS	13,002.60
LABOR CHARGES	4,870.00

Grand Total: 17,872.60 (SGD)

30/12/2022 @ 1730m

H4 Andri

7/P Part

3 days
5

yn

Check part prices

2Kk Andri




ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
Email: alfredauto@hotmail.com

Tyre &
Sports Rim



We shall be glad if you can forward the payment at your early convenience.

ACKNOWLEDGED BY	DATE	ALFRED AUTO SERVICES & SUPPLIES
		Alfred Quah

Note: Full payment must be completed 7 days from the invoice date. There will be an interest of 1.5% imposed per month on overdue invoice. Thank you.

Payment Method

1. PAYNOW via UEN 39108900E

2. Bank Wire Transfer - (SGD Account)

Beneficiary/Company Name	Alfred Auto Services & Supplies
UEN no.	39108900E
Beneficiary's Bank Name	OCBC Bank
Account No.	620-453233-001
Bank Code	7339
Branch Code	620
Swift Code	OCBCSGSG