

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTMSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807**Our File No:** CS/MSG22013038/RVY3E2**Date:** 26/04/2023REFERENCE

Insured/Claimant:	GARDENIA FOODS (S) PTE LTD	Policy No:	30001972213	
Date of Loss:	24/12/2022	Nature of Claim:	OD	Claim No: 297293

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBF4160P		
Make & Model:	MITSUBISHI CANTER, 3.0 D FEA01BR2SDEB (CBU) (M)		
Reg. Date:	14/10/2016 (Man. Year: 2016)	Engine No:	4P10C32893
Colour:	Red	Chassis No:	FEA01BA20354
Engine Capacity:	2998 cc	Odometer:	114220 km
Market Value/New Car Price:	S\$46,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	DURATURN 7 mm	Rear Left Side:	DURATURN 7/7 mm
Front Right Side:	DURATURN 7 mm	Rear Right Side:	DURATURN 7/7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,277.60	3,460.00	4,817.60	58.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,110.00	1,760.00	1,350.00	43.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,387.60	5,220.00	6,167.60	54.16
- Excess (S\$)	1,500.00	1,500.00	0.00	0.00
(S\$)	9,887.60	3,720.00	6,167.60	62.38
+ GST 7.00/8.00% (S\$)	692.13	297.60	394.53	57.00
Nett Amount (S\$)	10,579.73	4,017.60	6,562.13	62.03

INSPECTION

Date of Assignment:	30/12/2022	Present Location:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)
Date Inspected:	30/12/2022	Inspected At:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) Blk 3 Pioneer Road North, #01-18 Singapore 628457
Estimated Period of Repair:	6.0 days		

Adjuster: MOHD RASUL**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 26 Apr 2023)	
Parts:	N/A	mitsubishi canter 3.0 D FEA01BR2SDEB (CBU) (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBF4160P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOX @ FRT PANEL UPPER (OUTER)	Bent	600.00 FS	*600.00 FS
2	1		*REAR BOX @ FRT PANEL LOWER (OUTER)	Bent	600.00 FS	*600.00 FS
3	1		*REAR BOX PILLAR RH	Bent	1,400.00 FS	*1,400.00 FS
4	2		*REAR BOX SLIDING DOOR RH	Repair	2,400.00 FS	*- FS
5	2		*REAR SLIDING DOOR LOCK PIN	Broken	160.00 FS	*160.00 FS
6	1		*REAR SLIDING DOOR BOTTOM RUN CHANNEL	Not Necessary	500.00 FS	*- FS
7	1		*REAR SLIDING DOOR TOP RUN CHANNEL	Not Necessary	500.00 FS	*- FS
8	1		*REAR BOX @ FRT PANEL UPPER (INNER)	Bent	600.00 FS	*600.00 FS
9	1		*REAR BOX @ FRT PANEL LOWER (INNER)	Not Necessary	600.00 FS	*- FS
10	1		*REAR BOX PILLAR FRAME (RH)	Repair	800.00 FS	*- FS
11	1		*REAR RIVETS	Necessary	100.00 FS	*100.00 FS
Supplementary #1						
12	1		*1005 FRT HEADLAMP LWR APRON RH (WCP)	Not Necessary	16.00 F	*- F

F=Franchise part. S=SpcNett.

Sub Total (S\$)	8,276.00	3,460.00
+ Margin on L,N Items 10.00/0.00% (S\$)	1.60	0.00
Total Parts (S\$)	8,277.60	3,460.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK, WELD, REMOVE & REPLACE ABOVE PARTS	New	1,200.00	800.00
2	TO SPRAY PAINTING ON AFFECTEDS AREAS	New	1,200.00	600.00
3	TO REDRAW LOGO ON BOTH DOORS	New	650.00	300.00
4	TO REMOVE & REFIX PANEL GLASS	New	60.00	60.00
Gross Labour Cost (\$\$)			3,110.00	1,760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >