

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Kwok Woon Choo

Date: 03 Jan 2023

Preliminary Advice

Vehicle No	: GBF4160P	Accident Date	: 24/12/2022
Make	: MITSUBISHI CANTER	Policy No.	: 30001972213
Assignment Date	: 30/12/2022	Excess	: S\$1,500.00
Date of Inspection	: 30/12/2022	Est. Duration of Repair	: 6
Inspection At	: SNG AH TEE MOTOR & PANEL SERVICE PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,370.00
Revised Amount	:S\$	5,220.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,220.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	46,000.00
COE / PARF Rebate	:S\$	18,877.00
Salvage Value	:S\$	
Margin for Repair	:S\$	27,123.00

Remarks

- (X) The vehicle is economical for repair
 () The vehicle is not economical for repair
 (X) Part-by-Part repair
 () Lump Sum repair

- (X) The above survey was conducted on a 'without prejudice' basis.

Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost .