

REPAIR DETAILS

Ram / Viron LK
2/0 MSIG

Reference

Part Source: (Last Synchronised: 30 Dec 2022)
Parts: N/A MITSUBISHI CANTER 3.0 D FEA01BR2SDEB (CBU) (M) (Model not available in database)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Sng Ah Tee Motor & Panel Service Pte Ltd/GBF4160P/30/12/2022 11:30
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BOX @ FRT PANEL UPPER (OUTER) <i>bt</i>	0	0.00	*600.00 FS
2	1		*REAR BOX @ FRT PANEL LOWER (OUTER) <i>bt</i>	0	0.00	*600.00 FS
3	1		*REAR BOX PILLAR RH <i>bt</i>	0	0.00	*1,400.00 FS
4	2		*REAR BOX SLIDING DOOR RH <i>repair</i>	0	0.00	*2,400.00 FS X
5	2		*REAR SLIDING DOOR LOCK PIN <i>bro</i>	0	0.00	*160.00 FS
6	1		*REAR SLIDING DOOR BOTTOM RUN CHANNEL <i>X nn</i>	0	0.00	*500.00 FS X
7	1		*REAR SLIDING DOOR TOP RUN CHANNEL <i>X nn</i>	0	0.00	*500.00 FS X
8	1		*REAR BOX @ FRT PANEL UPPER (INNER) <i>bt</i>	0	0.00	*600.00 FS
9	1		*REAR BOX @ FRT PANEL LOWER (INNER) <i>X nn</i>	0	0.00	*800.00 FS R
10	1		*REAR BOX PILLAR FRAME (RH) <i>repair</i>	0	0.00	*100.00 FS
11	1		*REAR RIVETS <i>re</i>	0	0.00	

F=Franchise part, S=SpcNett.

Sub Total (\$\$) *\$ 3460 + snell* 8,260.00
+ Margin on L,N Items 10.00% (\$\$) 0.00
Total Parts (\$\$) 8,260.00

Sng Ah Tee Motor & Panel Service Pte Ltd/GBF4160P/30/12/2022 11:30. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1	TO KNOCK, WELD, REMOVE & REPLACE ABOVE PARTS	New	800	1,200.00
2	TO SPRAY PAINTING ON AFFECTEDS AREAS	New	600	1,200.00
3	TO REDRAW LOGO ON BOTH DOORS	New	300	650.00
4	TO REMOVE & REFIX PANEL GLASS	New		60.00

Gross Labour Cost (S\$) ^{Labour} \$1,760 3,110.00

Sng Ah Tee Motor & Panel Service Pte Ltd/GBF4160P/30/12/2022 11:30. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

total \$5200/
part by part
before item \$1500
ok? pls revert
Shawn
20/12/2022

Rahul
H# 90010068
6 days
P/P
30/12/22 P/SSC
EXCESS: 1500
Revers
Reg before
paint

REPAIR DETAILS**Reference****Part Source:** (Last Synchronised: 16 Feb 2023)**Parts:** N/A MITSUBISHI CANTER 3.0 D FEA01BR2SDEB (CBU) (M) (Model not available in database)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Sng Ah Tee Motor & Panel Service Pte Ltd/GBF4160P/16/02/2023 17:42**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1005 FRT HEADLAMP LWR APRON RH	0.00	0.00	*16.00 F nn
						F=Franchise part.
						Sub Total (\$\$)
						16.00
						+ Margin on L,N Items 10.00% (\$\$)
						1.60
						Total Parts (\$\$)
						17.60

Sng Ah Tee Motor & Panel Service Pte Ltd/GBF4160P/16/02/2023 17:42. Not valid without Reference section.
Generated using Merimen e-Claims IEAS