

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22013039/UWP3Q2**Date:** 16/01/2023**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00106752201

**Claimant Vehicle
No :** SLH2703H**Insured
Vehicle No :** SJL729A

Date of Loss: 18/12/2022

Nature of Claim: TP

Claim
No: SNM22D209111/C02/LEWLC**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SLH2703H**

Make & Model: CITROEN C4 PICASSO, 1.6 BLUEHDI EAT6 (A) Engine No: 10JBHD3051542

Reg. Date: 28/10/2016 (Man. Year: 2016)

Chassis No: VF73DBHGTGJ655784

Colour: White

Odometer: 163456 km

Engine Capacity: 1560 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size: 205/60 R16

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,773.20	1,485.40	5,287.80	78.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,180.00	550.00	1,630.00	74.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,953.20	2,035.40	6,917.80	77.27
Approved Total (Overridden) (S\$)		1,600.00		
Nett Amount (S\$)	8,953.20	1,600.00	7,353.20	82.13

INSPECTION

Date of Assignment: 30/12/2022

Date Inspected: 03/01/2023 Inspected At:

8 KAKI BUKIT AVENUE 4
#02-37 PREMIER @ KAKI BUKIT SINGAPORE
415875
Repairer: Prompt Auto Solutions Pte Ltd

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** XinYu*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Jan 2023)
Parts:	143	CITROEN C4 PICASSO 1.6 BLUEHDI EAT6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLH2703H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Not Necessary	974.00 FL	*- FL
2	1		*FRONT BUMPER	Dented / Deformed	924.00 FL	*924.00 FL
3	1		*SET FRONT BUMPER CLIPS	Necessary	60.00 FL	*60.00 FL
4	1		*FRONT BUMPER RH FOG LAMP	Not Necessary	335.00 FL	*- FL
5	1		*FRONT BUMPER RH FOG LAMP COVER	Not Necessary	94.00 FL	*- FL
6	1		*FRONT BUMPER LH FOG LAMP	Not Necessary	335.00 FL	*- FL
7	1		*FRONT BUMPER LH FOG LAMP COVER	Not Necessary	94.00 FL	*- FL
8	1		*FRONT BUMPER RH SIDE RETAINER	Not Necessary	67.00 FL	*- FL
9	1		*FRONT BUMPER LH SIDE RETAINER	Not Necessary	67.00 FL	*- FL
10	1		*FRONT BUMPER CENTRE LOWER GRILLE	Twisted	263.00 FL	*263.00 FL
11	1		*FRONT BUMPER REINFORCEMENT	Bent	359.00 FL	*359.00 FL
12	1		*RH HEADLAMP	Not Necessary	1,132.00 FL	*- FL
13	1		*LH HEADLAMP	Not Necessary	1,132.00 FL	*- FL
14	1		*FRONT GRILLE WITH CHROME	Not Necessary	366.00 FL	*- FL
15	1		*SET FRONT GRILLE CLIPS	Not Necessary	40.00 FL	*- FL
16	1		*AIRCON CONDENSER	Not Necessary	1,206.00 FL	*- FL
17	1		*FRONT NUMBER PLATE	Bent	70.00 FS	*40.00 FS
					Sub Total (\$\$)	
					7,518.00	1,646.00
					- List Item Discount on L Items 10.00/10.00% (\$\$)	
					744.80	160.60
					Total Parts (\$\$)	
					6,773.20	1,485.40

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES ON AFFECTED AREAS AND REPLACED PARTS AS LISTED	New	1,000.00	300.00
2	RE-SPRAY AFFECTED AREAS AND PARTS	New	1,000.00	250.00
3	REMOVE AND REPLACE AIRCON CONDENSER AND PIPES TO REPAIR	New	180.00	0.00
Gross Labour Cost (S\$)			2,180.00	550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >