

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/CTI22013045/DQP3Q2**Date:** 17/02/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00017922201
Claimant Vehicle No :	SNC3405P	Insured Vehicle No :	SKA2165J
Date of Loss:	28/12/2022	Nature of Claim:	TP
		Claim No:	SNM22D209362/C02/KHONGLH

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNC3405P		
Make & Model:	AUDI A7 SPORTBACK, 3.0 TFSI QU (A)	Engine No:	DLZ010945
Reg. Date:	21/12/2018 (Man. Year: 2018)	Chassis No:	WAUZZZF28KN025368
Colour:	Black	Odometer:	54800 km
Engine Capacity:	2995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/40 R20	Rear Tyre Size:	255/40 R20
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,350.75	3,869.01	1,481.74	27.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,300.00	1,100.00	1,200.00	52.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,650.75	4,969.01	2,681.74	35.05
Approved Total (Overridden) (S\$)		3,950.00		
(S\$)	7,650.75	3,950.00	3,700.75	48.37
+ GST 8.00/8.00% (S\$)	612.06	316.00	296.06	48.37
Nett Amount (S\$)	8,262.81	4,266.00	3,996.81	48.37

INSPECTION

Date of Assignment:	01/01/2023		
Date Inspected:	04/01/2023	Inspected At:	ST Powered Pte Ltd (HQ) 128 Woodlands Ind Park E5 Singapore 757851
Estimated Period of Repair:	4.0 days		

Adjuster: BRYAN TANI**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Feb 2023)
Parts:	143	AUDI A7 SPORTBACK 3.0 TFSI QU (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNC3405P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	2,356.98 FL	*2,265.60 FL
2	1		*REAR BUMPER INNER BRACKET	Serviceable	356.70 FL	*- FL
3	1		*REAR BUMPER LOWER SPOILER	Distorted	1,189.30 FL	*666.40 FL
4	2		*REAR PARKING SENSOR	Damaged	469.80 FL	*469.80 FL
5	1		*REAR REINFORCEMENT	Bent	897.10 FL	*897.10 FL
6	1		*REAR END PANEL	Repair	675.40 FL	*- FL
					Sub Total (\$\$)	5,945.28 4,298.90
					- List Item Discount on L Items 10.00/10.00% (\$\$)	594.53 429.89
					Total Parts (\$\$)	5,350.75 3,869.01

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO DISMANTLE & REPLACED ALL ACCIDENT DAMAGED PARTS	New	1,500.00	600.00
2	LABOUR TO PUTTY & SPRAY PAINTING ON THE ACCIDENT DAMAGED PARTS & REPLACED PARTS	New	800.00	500.00
Gross Labour Cost (S\$)			2,300.00	1,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >