

ASS. REC. BY:

REP: CS/CTI22013045/DGP³

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: 3NC3405P Yr Regn: Dec / 2018

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Andi A7 c.c. 2995

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 54800 T/Radio: Insured / Std / NI / NA

Eng/No: DL2010945

C/No: WAUZZZF28KN025368

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 255 / 40 R 20

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Michelin

Front

Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 28/12/2022 D.O.I. 28/12/2022 04/01/2023

Survey held at ST Powered Woodlands

Des. of Damages: Ren Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

China Taping SKA 2165J

15/02/23

Analysed 215 3,950/- with 4 days of rep.
(Red 27700.75, 48%)

Date/Time, File Pass to?

1) 15/2/2023

Date/Time, File Return to?

2)



: Prel. Report



: Final Report

Days Of Repair: 4

Resurvey No. of Trip: 2

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Inve (\$

Survey Fee:

Transportation:

S + RS: \$

Photos

Others

Report Form: MRP-TP

Report Form: MRP-TP

ST Powered Motoring Pte Ltd

128 Woodlands Industrial Park E5

Singapore 757851

Tel: 91005500

Email: stpmotoring@gmail.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date: 29/12/2022

To: Motor Claims Department
China Taiping Insurance

RE: Estimate repair cost of SNC3405P

Your Insured: SKA2165J

Dear Sir/Madam,

Vehicle No: SNC3405P

Make Model: Audi A7

Date of accident: 28-12-2022

We are pleased to quote you the repair cost for the above-mentioned vehicle:

Qty	Description	Unit Price	TOTAL
1	Rear bumper <i>distorted</i>	<i>2265.60</i>	\$ 2,356.98
1	Rear bumper inner bracket <i>sc</i>		\$ 356.70
1	Rear bumper lower spoiler <i>distorted</i>	<i>666.40</i>	\$ 1,189.30
2	Rear parking sensor <i>Dam</i>	234.9	\$ 469.80
1	Rear reinforcement <i>bt</i>		\$ 897.10
1	Rear end panel <i>ly</i>		\$ 675.40
	Sub-total before discount		\$ 5,945.28
		<i>4298.90</i>	
	Parts percentage discount 10%	<i>3869.01</i>	\$ 594.53
	PARTS TOTAL		\$ 5,350.75
	LABOUR CHARGES & MISC		
1	Labour to dismantle & replaced all accident damaged parts		\$ 1,500.00
2	Labour to putty & spray painting on the accident damaged parts & replaced parts		\$ 800.00
	LABOUR TOTAL	<i>1100.00</i>	\$ 2,300.00
	LABOUR & PARTS TOTAL		\$ 7,650.75

Regards,
Terrence Lim

04/01/2023 @ 1000hrs

Not Author

21mm

Tygar 4 days.

2 Kic Ande

4969.01

4/s 3950/-

600/-

500/-