

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EGI22013047/UNY3E2**Date:** 30/01/2023REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : GBD7821G**Insured Vehicle No :** XE3293R

Date of Loss: 06/12/2022

Nature of Claim: TP

Claim No: CDMFG22002626-001

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **GBD7821G**

Make & Model: FIAT DOBLO, 1.6 D CARGO MJ (M)

Engine No: 263A50007220834

Reg. Date: 08/05/2015 (Man. Year: 2015)

Chassis No: ZFA26300006978482

Colour: Black

Odometer: 190368 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60R16

Rear Tyre Size: 195/60R16

Front Left Side: Transway 6 mm

Rear Left Side: Nexen 6 mm

Front Right Side: Transway 6 mm

Rear Right Side: Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,355.60	4,238.42	3,117.18	42.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,800.00	1,020.00	780.00	43.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,155.60	5,258.42	3,897.18	42.57
Approved Total (Overridden) (S\$)		4,200.00		
(S\$)	9,155.60	4,200.00	4,955.60	54.13
+ GST 8.00/8.00% (S\$)	732.45	336.00	396.45	54.13
Nett Amount (S\$)	9,888.05	4,536.00	5,352.05	54.13

INSPECTION

Date of Assignment: 30/12/2022

Date Inspected: 03/01/2023 Inspected At:

Liu's Brother Auto Engineering Workshop (kaki Bukit)
(HQ)Blk 1 Kaki Bt Ave 6 #01-01 Auto Bay @ Kaki Bt
Singapore 417883, Kaki Bukit
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 11 Jan 2023)	
Parts:	N/A	FIAT DOBLO 1.6 D CARGO MJ (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBD7821G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Bent/Buckled	1,170.00 F	*1,067.55 FL
2	2		*FRONT HEAD LAMP	Holder Cracked	1,724.80 F	*1,724.80 FL
3	1		*FRONT BUMPER	Dented/Deformed	1,245.50 F	*864.07 FL
4	1		*SET FRONT BUMPER CLIPS	Necessary	65.00 F	*50.00 FL
5	1		*FRONT BUMPER REINFORCEMENT	Bent	752.00 F	*752.00 FL
6	2		*FRONT BUMPER BRACKET	Not Necessary	343.60 F	*- FL
7	1		*FRONT BUMPER SPONGE	Torn	117.60 F	*117.60 FL
8	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	685.00 F	*- FL
9	1		*FRONT GRILLE	Not Necessary	845.00 F	*- FL
10	1		*FRONT GRILLE FIAT LOGO MOTIF	Not Necessary	142.10 F	*- FL
11	1		*SET FRONT BUMPER LOWER GRILLE CLIPS	Not Necessary	65.00 FS	*- FS
12	1		*FRONT CORPORATE ADVERTISEMENT & ARTWORK	Necessary	200.00 FS	*120.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	7,355.60	4,696.02
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	457.60
Total Parts (\$)	7,355.60	4,238.42

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK ALL WIRING & ELACTRICAL COMPONENT FOR PROPER FUNCTION	New	80.00	20.00
2	REMOVE & REFIX FRONT BONNET COMPONENTS	New	60.00	0.00
3	LABOR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN & REPLACING PARTS ETCS	New	800.00	420.00
4	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS	New	800.00	550.00
5	TO APPLY RUST PROOFING,RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	60.00	30.00
Gross Labour Cost (S\$)			1,800.00	1,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >