

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/1190/2022/EQ
DATE : 5-Jan-23
WIP : 57017

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 5/1/2023
YOUR INSURED VEH NO : XD 9535 J

Allianz Insurance Singapore Pte Ltd
79 Robinson Road
#09-01
Singapore 068897
Attn: Motor Claims Dept

OWNER'S NAME : MR NG SIANG TIAN (HUANG XIANGDIAN)
ADDRESS : BLK 120A KIM TIAN PLACE
#11-50
SINGAPORE 161120
TELEPHONE : HP +65 96836240
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO :
VEHICLE NO : **SMT 954 M**
MODEL CODE : AUDI A5 SPORTBACK 2.0 TFS
MODEL YEAR : 30/9/2022
ENGINE NO : DEM 034418
CHASSIS NO : WAUZZZF52NA002593
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 29-Dec-22
PLACE OF ACCIDENT : ALONG BRADDELL ROAD

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMT 954 M

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$	360.00	✓
2	TO RENEW REAR WINDSCREEN AND RHS 1/4 GLASS.	S/N \$	300.00	✓
3	TO INSTALL SOLAR FILM FOR ALL THE AFFECTED GLASSES.	S/N \$	400.00	✓
4	TO CARRY OUT WATER SEEPAGE FOR REAR WINDSCREEN.	S/N \$	200.00	✓
5	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$	1,600.00	✓
6	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, CD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$	1,600.00	✓
TOTAL LABOUR CHARGES		:	\$ 4,460.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMT 954 M

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO REMOVE AND TRANSFER RHS FRONT DOOR AND RHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 800.00	✓
8	TO DISMANTLE AND REINSTALL REAR BUMPER AND RHS SILL PANEL TRIM. TO RENEW RHS FRONT DOOR AND RHS REAR DOOR. TO CUT OUT AND WELD RHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 8,000.00	6400
9	TO RESPRAY REAR BUMPER, RHS REAR FENDER, RHS REAR DOOR, RHS FRONT DOOR, 2 DOOR HANDLES, RHS WING MIRROR COVER, RHS SILL PANEL, ROOF CHANNEL, DRAIN CHANNEL, DOOR ENTRANCES AND REAR END PANELLING.	\$ 8,000.00	5300
10	TO RE-APPLY PAINT COATING (BY OWNER).	S/N \$ 663.00	✓
11	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 22,115.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMT 954 M

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	FRONT DOOR - RH <i>Dented</i>	1	\$	3,977.00	✓
2	FRONT OUTER DOOR SEAL - RH <i>new</i>	1	\$	247.00	✓
3	BONDING AGENT <i>?</i>	1	\$	51.00	?
4	CLEANING SOLUTION <i>?</i>	1	\$	74.00	?
5	APPLICATOR <i>?</i>	1	\$	9.00	?
6	FRONT DOOR CATCH - RH <i>?</i>	1	\$	134.00	?
7	FRONT DOOR HANDLE TRIM PLATE - RH	1	\$	98.00	?
8	FRONT DOOR HANDLE COVER - RH	1	\$	7.00	?
9	FRONT DOOR HANDLE SENSOR - RH <i>?</i>	1	\$	255.00	?
10	FRONT DOOR HANDLE - RH <i>Damaged</i>	1	\$	47.00	✓
11	FRONT DOOR UNDERLAY - RH <i>?</i>	1	\$	4.00	?
12	REAR DOOR UNDERLAY - RH <i>?</i>	1	\$	4.00	?
13	FRONT DOOR MOUNTING BAR - RH <i>?</i>	1	\$	183.00	?
14	FRONT TYRE PRESSURE DATA PLATE <i>new</i>	1	\$	41.00	✓
15	FRONT DOOR CHROME TRIM - RH <i>new</i>	1	\$	171.00	✓
16	FRONT EXTERIOR WING MIRROR MOUNTING - RH <i>new</i>	1	\$	2,015.00	✓
17	FRONT WING MIRROR CAP - RH <i>new</i>	1	\$	308.00	+
18	FRONT WING MIRROR GLASS - RH <i>new</i>	1	\$	1,757.00	+
19	FRONT WINDOW REGULATOR - RH <i>new</i>	1	\$	392.00	+
20	FRONT WINDOW APERTURE SEAL - RH INNER <i>new</i>	1	\$	453.00	+
SUB TOTAL SPARE PARTS			:	\$ 10,227.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMT 954 M

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT WINDOW SLOT SEAL CHROME TRIM STRIP - RH <i>new</i>	1	\$ 446.00	<i>x.</i>
22	REAR DOOR - RH <i>Dented</i>	1	\$ 3,977.00	<i>✓</i>
23	REAR DOOR OUTER SEAL - RH <i>new</i>	1	\$ 247.00	<i>✓</i>
24	BONDING AGENT <i>?</i>	1	\$ 51.00	<i>?</i>
25	CLEANING SOLUTION <i>?</i>	1	\$ 74.00	<i>?</i>
26	APPLICATOR <i>?</i>	1	\$ 9.00	<i>?</i>
27	REAR DOOR ATTACHMENT PARTS <i>new</i>	1	\$ 180.00	<i>x</i>
28	REAR DOOR CATCH - RH <i>?</i>	1	\$ 134.00	<i>?</i>
29	REAR WHEEL HOUSING LINER - RH <i>new</i>	1	\$ 299.00	<i>x.</i>
30	REAR SIDE PANEL - RH <i>Dented</i>	1	\$ 4,076.00	<i>✓</i>
31	REAR QUARTER WINDOW - RH <i>new</i>	1	\$ 798.00	<i>✓</i>
32	WINDOW PRIMER <i>new</i>	1	\$ 22.00	<i>✓</i>
33	ATTACHMENT PARTS <i>?</i>	1	\$ 136.00	<i>?</i>
34	ADHESIVE TAPES	1	\$ 221.00	<i>✓</i>
35	ACRYLIC SEALANT <i>new</i>	S/N	\$ 180.00	<i>✓</i>
36	CAVITY WAX	S/N	\$ 140.00	<i>✓</i>
37	STONE CHIP	S/N	\$ 180.00	<i>✓</i>
38	METAL FILLER POWDER <i>new</i>	S/N	\$ 280.00	<i>✓</i>
39	1/4 GLASS SEALANT	S/N	\$ 100.00	<i>✓</i>
40	SUNDRIES <i>?</i>		\$ 500.00	<i>?</i>
TOTAL SPARE PARTS		:	\$ 22,277.00	
TOTAL LABOUR CHARGES		:	\$ 22,115.00	
GRAND TOTAL		:	\$ 44,392.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Li*
SURVEYED DATE : *05/01/23.*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 15 Days.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

Unique (Since 1995) Pte Ltd

53 Ubi Ave 1, #01-40 Paya Ubi Industrial Park S408934

QUOTATION

Invoice 001

Date 05.01.2023

VEHICLE NO	MAKE / MODEL	COLOR
SMT954M	Audi A5	D.Grey

NO	DESCRIPTION	QTY	Unit Price	AMOUNT
1	Titanium SH Maintenance 2 x Right Door Right Panel Bumper	1	\$ 663.00	\$ 663.00
			Total	\$ 663.00
			Discount	-
			Net Total	\$ 663.00

Remarks :

All remittance must be crossed "A/c Payee Not Negotiable"

and made payable to "Unique (Since 1995) Pte Ltd"

Unique (Since 1995) Pte Ltd

Sherine Chan

Authorised Signature

Enquiry: 68442235, Fax: 68427357, Phone Booking: 64631311, 67451311, Online Booking: www.cs2.sg

CS-II International

53, Ubi Ave 1, #01-40. Paya Ubi Industrial Park Singapore 408934
Web: www.cs2singapore.com, Email: info@cs2singapore.com

Customer: Siang Tian
Address:
Telephone: 96836240

Customer: Siang Tian
Address:
Telephone: 96836240

Invoice



Item #	Name / Description	Quantity	Unit Price	Sub-total
1	Titanium SH Coating - Executive SMT954M (D.Blue Audi A5) - x1	1	1,843.00	\$1,843.00
2	ClearVUE - Executive SMT954M (D.Blue Audi A5) - x1	1	150.00	\$150.00
3	RIM Coating (\$40/rim) SMT954M (D.Blue Audi A5) - x4	4	40.00	\$160.00
4	Leather Conditioning - Executive SMT954M (D.Blue Audi A5) - x1	1	48.00	\$48.00

Discount:	\$-821.00
Net Total:	\$1,380.00
SGD Total:	\$1,380.00

This is computer generated document no signature required.