

L/S um

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No.: SHA5748T

Make : HYUNDAI

Model : I-40

Date: 02/11/2022

Insurance: CHINA TAIPING

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	FRT BUMPER			\$ 1,052.20
20	BUMPER CLIPS			\$ 44.00
1	FRT BUMPER BRACKER LH			\$ 55.80
1	FRT DOOR LH			\$ 2,256.40
1	FRT FENDER LH			\$ 663.00
1	FRT DOOR MIRROR LH			\$ 670.00
1	REAR FENDER LH			\$ 2,171.40
1	RR BUMPER			\$ 553.00
1	REAR DOOR LH			\$ 2,416.80
2	WHEEL HUB CAP FRT LH / RR LH		\$ 214.20	\$ 428.40
	SUB TOTAL		5157.40	\$ 10,311.00
	LESS 20%		4125.92	\$ 2,062.20
	DISCOUNTED TOTAL			\$ 8,248.80
	TYRE FRT LH / RR LH		\$ 216.00	\$ 432.00
	REAR DOOR COMFORTDELGRO & APPS STICKER LH			\$ 80.00
	FRT DOOR COMFORT LOGO LH		155	\$ 75.00
				\$ 587.00
	Labour Charge			
	PANEL BEATING			\$ 1,200.00
	SPRAY PAINTING CHARGE			\$ 1,700.00
	CHECK ALL LIGHTING		2400	\$ 40.00
	TRANSFER OF DOOR			\$ 240.00
	TUFF KOTE			\$ 60.00
	TOTAL LABOUR		6680.92	\$ 3,240.00
	ESTIMATE TOTAL		1185350	\$ 12,075.80
			03 days	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanpin 97495749
 WVP 2/11/22 2430pm
 L/S Pong after repair
 Tanpin 11/11/22
 (3-4 days)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: