

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/1176/2022/EQ
DATE : 3-Jan-23
WIP : 57107

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 6/1/2023

YOUR INSURED VEH NO : GBD 9922 K

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MR RAY JOSEPH OOI RUI QIN
ADDRESS : 747C BEDOK RESERVOIR CRESCENT
#09-31
SINGAPORE 473747
TELEPHONE : HP +65 82331393
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : P10610835R01
VEHICLE NO : **SKJ 7696 M**
MODEL CODE : AUDI A3 SEDAN 1.0 TFSI
MODEL YEAR : 28/2/2020
ENGINE NO : CHZ C31144
CHASSIS NO : WAUZZZ8V3KA096749
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 30-Dec-22
PLACE OF ACCIDENT : ALONG BEDOK RESERVOIR ROAD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKJ 7696 M

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$	280.00	
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	350.00	
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND RHS HEADLIGHT. INSPECT FRONT LOCK CARRIER FOR DAMAGES. REINSTALL ALL PARTS REMOVED.	\$	2,100.00	
4	TO RESPRAY FRONT BUMPER AND BONNET.	\$	1,800.00	
5	TO CARRY OUT DIAGNOSTIC CHECK .	S/N \$	192.00	
TOTAL LABOUR CHARGES		:	\$ 4,722.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKJ 7696 M

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 2,432.00	
2	FRONT BUMPER FIXING PARTS	1	\$ 195.00	
3	FRONT BUMPER CLOSING ELEMENT - RH	1	\$ 318.00	
4	RADIATOR GRILLE	1	\$ 1,578.00	
5	RADIATOR GRILLE CLOSING ELEMENT	1	\$ 210.00	
6	AIR CONDITIONER STICKER	1	\$ 9.00	
7	CAUTION SIGN STICKER	1	\$ 16.00	
8	FRONT BUMPER REINFORCEMENT BEAM COVER	1	\$ 136.00	
9	FRONT BUMPER FOAM FILLER PIECE	1	\$ 211.00	
10	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 847.00	
11	HEADLIGHT - RH	1	\$ 5,879.00	
12	BONNET	1	\$ 3,348.00	
13	BONNET ATTACHMENT PARTS	1	\$ 172.00	
14	BONNET EDGE PROTECTION	1	\$ 31.00	
15	FRONT NO PLATE	S/N	\$ 60.00	
16	SUNDRIES		\$ 200.00	
TOTAL SPARE PARTS		:	\$ 15,642.00	
TOTAL LABOUR CHARGES		:	\$ 4,722.00	
GRAND TOTAL		:	\$ 20,364.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT