

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 19 Jan 2023)
 Parts: N/A HINO XZU710R 4.0 D 14FT WIDE CAB 5T (M) (Model not available in database)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for YP9365H)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT WINDSCREEN <i>con</i>	0.00	0.00	*1,640.00 F
2	1		*FRONT WINDSCREEN TOP MLDG <i>do</i>	0.00	0.00	*135.00 F
3	1		*FRONT WINDSCREEN LOWER MLDG <i>ne</i>	0.00	0.00	*135.00 F
4	2		*FRONT WINDSCREEN LH/RH MLDG <i>ne</i>	0.00	0.00	*250.00 F
5	2		*WIPER ARM LH/RH <i>X</i>	0.00	0.00	*560.00 F
6	2		*WIPER BLADE LH/RH <i>X</i>	0.00	0.00	*80.00 F
7	1		*FRONT PANEL <i>repair</i>	0.00	0.00	*585.00 F
8	1		*HINO STICKER <i>ne</i>	0.00	0.00	*65.00 F
9	1		*300 STICKER <i>ne</i>	0.00	0.00	*65.00 F
10	1		*MIRROR STAY LH <i>bt</i>	0.00	0.00	*450.00 F
11	1		*MIRROR STAY ASSY, RH <i>bt</i>	0.00	0.00	*1,600.00 F
12	2		*MIRROR STAY COVER LH/RH <i>mis</i>	0.00	0.00	*80.00 F
13	1		*SIDE VIEW MIRROR LH <i>br</i>	0.00	0.00	*433.00 F
14	1		*ROUND MIRROR <i>X</i>	0.00	0.00	*125.00 F
15	2		*CORNER PANEL LH/RH <i>con</i>	0.00	0.00	*1,080.00 F
16	2		*CORNER PANEL SPONGE LH/RH <i>ne</i>	0.00	0.00	*30.00 F
17	2		*CORNER PANEL TOP COVER LH/RH <i>mis</i>	0.00	0.00	*90.00 F
18	10		*CORNER PANEL CLIPS LH/RH <i>ne</i>	0.00	0.00	*25.00 F
19	1		*FRONT GRILLE <i>X</i>	0.00	0.00	*710.00 F
20	2		*FRONT GRILLE SEAL <i>X</i>	0.00	0.00	*31.00 F
21	10		*FRONT GRILLE CLIPS <i>X</i>	0.00	0.00	*25.00 F
22	1		*HINO LOGO <i>X</i>	0.00	0.00	*90.00 F
23	2		*HEADLAMP LH/RH <i>con</i>	0.00	0.00	*2,172.00 F
24	2		*FRONT DOOR RH/LH <i>bt</i>	0.00	0.00	*1,900.00 F
25	1		*EURO 6 DECAL <i>ne</i>	0.00	0.00	*60.00 F
26	2		*616 STICKER <i>ne</i>	0.00	0.00	*120.00 F
27	1		*SIDE STEP RH <i>SCA</i>	0.00	0.00	*120.00 F
28	1		*FRONT BUMPER <i>TOUR</i>	0.00	0.00	*550.00 F
29	1		*FOG LAMP RH	0.00	0.00	*312.80 F
30	1		*FOG LAMP COVER RH	0.00	0.00	*18.00 F
31	1		*FOG LAMP BRKT RH	0.00	0.00	*38.00 F
32	1		*FRONT BUMPER STAY RH	0.00	0.00	*310.00 F
33	2		*FRONT BUMPER STAY GROMMET <i>ne</i>	0.00	0.00	*11.00 F
34	1		*ROOF PANEL <i>br</i>	0.00	0.00	*1,580.00 F
35	1		*ROOF PANEL, LAMP LH <i>con</i>	0.00	0.00	*55.00 F
36	1		*ROOF LINING <i>de</i>	0.00	0.00	*780.00 F
37	10		*ROOF LINING CLIP <i>ne</i>	0.00	0.00	*25.00 F
38	1		*LH A-PILLAR (OUTER LAYER) <i>H</i>	0.00	0.00	*580.00 F
39	1		*LH A-PILLAR (REINFORCEMENT) <i>bt</i>	0.00	0.00	*450.00 F
40	1		*LH A-PILLAR (INNER LAYER) <i>bt</i>	0.00	0.00	*550.00 F
41	1		*LH A-PILLAR INNER TRIM <i>con</i>	0.00	0.00	*320.00 F
42	1		*LH A-PILLAR INNER GRIP HANDLE <i>X</i>	0.00	0.00	*180.00 F
43	1		*LH SUN VISOR, SHELF <i>con</i>	0.00	0.00	*550.00 F
44	1		*LH FRONT DOOR RUBBER <i>ne</i>	0.00	0.00	*95.00 F
45	1		*LH FRONT DOOR GLASS <i>br</i>	0.00	0.00	*350.00 F
46	1		*LH FRONT DOOR GLASS OUTER MLDG <i>ne</i>	0.00	0.00	*150.00 F
47	1		*LH FRONT DOOR QTR TRIM <i>mis</i>	0.00	0.00	*85.00 F
48	1		*LH FRONT DOOR FRAME SEAL <i>ne</i>	0.00	0.00	*65.00 F
49	1		*LH FRONT DOOR TRIM	0.00	0.00	*550.00 F
50	1		*LH FRONT DOOR, WINDOW REGULATOR	0.00	0.00	*280.00 F
51	1		*LH FRONT DOOR LOCK	0.00	0.00	*185.00 F
52	2		*LH FRONT DOOR HINGE UPPER/LOWER	0.00	0.00	*120.00 F
53	1		*DASHBOARD	0.00	0.00	*1,050.00 F
54	1		*DASHBOARD REINFORCEMENT	0.00	0.00	*80.00 F
55	1		*LH B-PILLAR <i>bt</i>	0.00	0.00	*550.00 F

F=Franchise part.

Sub Total (\$\$) 22,525.80
 + Margin on L,N Items 10.00% (\$\$) 2,252.58

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

1/19/23, 1:59 PM

Estimate Report

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
Total Parts (S\$)						24,778.38

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

No	Qty	Particulars	Amount
1	2	BIZ SAFE STAR <i>MC</i>	30 280.00
2	1	C-25422 LOGO <i>MC</i>	60 120.00
3	1	CAMERA RECORDER <i>MIS</i>	1,200.00
4	1	CAUTION STICKER <i>MC</i>	40.00
5	1	CM/SP SITCKER <i>MC</i>	50 120.00
6	1	COMPANY GRAPHIC LOGO - LH DOOR <i>MC</i>	120 280.00
7	1	COMPANY GRAPHIC LOGO - RH DOOR <i>MC</i>	120 280.00
8	1	FRONT WINDSCREEN PRIMER <i>MC</i>	30.00
9	1	FRONT WINDSCREEN SEALANT <i>MC</i>	40.00
10	1	IU BRACKET <i>MC</i>	40.00
11	1	REFLECTIVE STICKER YELLOW,BLACK	40 50.00
Sub Total (\$\$)			2,460.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO REPLACE FRONT WINDSCREEN	New	120 150.00
2	TO KNOCK/ CUT/ WELD ROOF PANEL, LH A-PILLAR INNER/ REINF/ OUTER, B-PILLAR, TO REPLACE DAMAGED PARTS RELATED TO ACCIDENT AND REALIGN ALL THE CONNECTION	New	1800 2000.00
3	TO REMOVE AND REPLACE DASHBOARD <i>plus</i>	New	200 250.00
4	TO REMOVE INTERIOR INNER TRIM, ROOF LINING AND SEAT TO ASSIST REPAIR	New	150 250.00
5	TO REPLACE & TRANSFER LH DOOR FILM/ LOCK/ ETC. TO NEW UNITS	New	60 80.00
6	TO APPLY ANTI RUST PROOFING ON AFFECTED AREAS	New	100 150.00
7	TO APPLY BODY SEALANT ON CUTTING AREAS	New	100 150.00
8	TO ADJUST FOCUS HEADLAMP	New	40 80.00
9	TO INSTALL IN CAR CAMERA SYSTEM <i>plus</i>	New	200 250.00
10	TO CHECK FOR AND RECTIFY WIRING FAULT, DIAGNOSE AND RESET SYSTEM AFTER REPAIR	New	80 180.00
Gross Labour Cost (\$\$)			3,540.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Paul
HP 90010068
15 days
4/8
19/01/23 @ 1600
Resy after repair

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	394Z
Vehicle Details	
Vehicle No.:	YP9365H
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Jan 2023
Vehicle Make:	HINO
Vehicle Model:	XZU710R 14FT WIDE CAB 5T
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	N04CVV10311
Chassis No.:	JHHUCV3H10K027216
Maximum Power Output:	-
Open Market Value:	\$30,800.00
Original Registration Date:	05 Sep 2018
First Registration Date:	05 Sep 2018
Transfer Count:	0
Actual ARF Paid:	\$1,540.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	04 Sep 2028
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$30,389.00
COE Rebate Amount:	\$17,098.00
Total Rebate Amount:	\$17,098.00

The information contained herein is correct as at 19 Jan 2023

Hino XZU710R

Overview

Financial

Accessories

Similar

Research

Photos

Map

ABWIN 論輝

YOUR FIRST CHOICE AT AUTOMOTIVE SERVICE PROVIDER



Price	\$89,800	Lifespan ⓘ	29-Apr-2039
Depreciation ⓘ	\$14,300 /yr View models with similar depre	Reg Date	30-Apr-2019 (6yrs 3mths 10days COE left)
Mileage	N.A.	Manufactured ⓘ	2019
Road Tax ⓘ	N.A.	Transmission	Manual
Dereg Value ⓘ	\$13,862 as of today (change)	Fuel Type	Diesel
COE ⓘ	\$22,075	OMV ⓘ	\$33,779
Engine Cap	4,009 cc	ARF ⓘ	\$1,689
Curb Weight ⓘ	2,500 kg	No. of Owners ⓘ	1