

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG23000019/UYA3Q2**Date:** 17/04/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7220046612
Claimant Vehicle No :	FBJ2175P	Insured Vehicle No :	SKA9277Z
Date of Loss:	22/12/2022	Nature of Claim:	TP
		Claim No:	2983456004SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBJ2175P	Engine No:	50C684515
Make & Model:	YAMAHA JUPITER MX, 134cc HC	Chassis No:	MH350C004DK684342
Reg. Date:	12/02/2014 (Man. Year: 2013)	Odometer:	34037 km
Colour:	Multi-colour		
Engine Capacity:	134 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	80-90-17	Rear Tyre Size:	100-80-17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,422.40	2,678.40	2,744.00	50.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,010.00	300.00	710.00	70.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,432.40	2,978.40	3,454.00	53.70
Approved Total (Overridden) (S\$)		2,300.00		
Nett Amount (S\$)	6,432.40	2,300.00	4,132.40	64.24
+ Loss of Use (5.0 x S\$20.00/day) (S\$)		100.00		
+ Other Costs (S\$)		70.00		
Nett Liability (S\$)		2,470.00		

INSPECTION

Date of Assignment:	03/01/2023	Erofia Motor Trading Pte Ltd - (kaki Bukit) (HQ)
Date Inspected:	03/01/2023 Inspected At:	1 Kaki Bukit Avenue 6, #02-62 AutoBay @ Kaki Bukit
Estimated Period of Repair:	4.0 days	Singapore 417883

Adjuster: MARCUS CHUA**Manager:** Ezlyna*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*FRONT FORK TUBE ASSY	Bent / Twisted	680.00 FL	*520.00 FL
2	1		*FORK UNDER BRACKET	Bent / Twisted	225.00 FL	*145.00 FL
3	1		*FRONT WHEEL RIM	Not Necessary	380.00 FL	*- FL
4	1		*FRONT RIM SHAFT	Not Necessary	85.00 FL	*- FL
5	1		*FRONT RIM BEARING	Not Necessary	68.00 FL	*- FL
6	1		*FRONT BRAKE DISC	Not Necessary	185.00 FL	*- FL
7	1		*HANDLE-BAR	Bent	155.00 FL	*155.00 FL
8	1		*SET HANDLE-BAR END	Cut	120.00 FL	*30.00 FL
9	1		*SET HAND GRIP	Not Necessary	65.00 FL	*- FL
10	1		*HEADLAMP	Cracked	280.00 FL	*280.00 FL
11	1		*FRONT HORN COVER INNER N/S	Cut	135.00 FL	*135.00 FL
12	2		*SIDE MIRRORS - R/L	Cut	140.00 FL	*80.00 FL
13	1		*BRAKE LEVER	Cracked	95.00 FL	*95.00 FL
14	1		*SET FAIRING ASSY	Cracked	680.00 FL	*500.00 FL
15	1		*FRONT FOOTREST BAR	Bent	185.00 FL	*145.00 FL
16	2		*FRONT FOOTREST RUBBER	Torn	95.00 FL	*60.00 FL
17	1		*BRAKE PEDAL	Cut	135.00 FL	*90.00 FL
18	1		*REAR FOOTREST	O/S Cut	140.00 FL	*48.00 FL
19	1		*EXHAUST ASSY	Repair	780.00 FL	*- FL
20	1		*EXHAUST COVER - CHROME	Bent	98.00 FL	*98.00 FL
21	1		*EXHAUST COVER CENTRE	Scratched	85.00 FL	*85.00 FL
22	1		*HANDLE-BAR BRACKET	Not Necessary	125.00 FL	*- FL
23	1		*SET NUMBER PLATE	Necessary	38.00 FS	*10.00 FS
24	1		*FORK OILS	Not Necessary	48.00 FS	*- FS
25	1		*FORK OIL SEALS	Not Necessary	78.00 FS	*- FS
26	1		*SET STEERING CONE	Necessary	120.00 FS	*80.00 FS
27	1		*GRAB FOOD DELIVERY BAG	Serviceable	180.00 FS	*- FS
28	1		*REAR BOX BRACKET	Cut	180.00 FS	*150.00 FS
29	1		*STICKER	Necessary	120.00 FS	*120.00 FS
30	1		*REAR FOOTREST BRACKET	O/S Cracked	240.00 FL	*110.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	5,940.00	2,936.00
- List Item Discount on L Items 10.00/10.00% (\$)	517.60	257.60
Total Parts (\$)	5,422.40	2,678.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND RESET HEADLAMP FORCUSING	New	80.00	0.00
2	TO REPAIR BODY FRAME	New	450.00	0.00
3	TO PROVIDE LABOUR	New	480.00	300.00
Gross Labour Cost (S\$)			1,010.00	300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >