



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2302852

INV Date 08/05/2023

Reference CC4/LPC23000020/Upa3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. GBF 4925A

Insured Veh. SLB 6764L

Claim No. 22/22/23/VP05/026783

Policy No. Z22VP05032258

Accident Date 30/12/2022

Inspection Date 03/01/2023

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (8%)	32.00
Grand Total	432.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CC4/LPC23000020/Upa3q2 Date: 08/05/2023 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLB 6764L	Veh. Inspected	GBF 4925A	
Policy No.	Z22VP05032258	Coverage (\$)	0.00	
Claim No.	22/22/23/VP05/026783	Excess (\$)	0.00	
Assign From	ENG HUEY NI	Assign Date	03/01/2023	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE (M)	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JTFHT02P400212797	Colour	SILVER	
Odometer	634020 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15	MICHELIN	6 mm	
L/H Front Tyre	195 R15	MICHELIN	6 mm	
R/H Rear Tyre	195 R15	MICHELIN	6 mm	
L/H Rear Tyre	195 R15	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION & N/S BODY.THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	30/12/2022	Inspection Date	03/01/2023	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			7 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBF 4925A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DEFORMED / TORN	755.20	681.10
1	FRONT BUMPER SIDE RETAINER N/S	CRACKED	108.50	108.50
1	SET FRONT BUMPER CLIPS	NECESSARY	50.00	50.00
1	FRONT MUDFLAP N/S	TORN	152.80	142.80
1	HEADLAMP N/S	CRACKED	1,201.10	899.00
1	FRONT DOOR N/S	DENTED / BENT	1,655.10	1,545.10
2	FRONT DOOR HINGES @\$105.00	NOT NECESSARY	210.00	-
1	FRONT DOOR REAR PILLAR OUTER N/S	BADLY DENTED	988.10	892.50
1	FRONT DOOR REAR PILLAR INNER N/S	TO REPAIR SEE LABOUR	855.20	-
1	FRONT STEP GARNISH N/S	GRAZED	288.90	288.90
1	FUEL LIP	NOT NECESSARY	185.00	-
1	SLIDING DOOR N/S	BADLY DENTED	1,845.10	1,660.10
1	SLIDING DOOR INNER TRIM N/S	NOT NECESSARY	488.10	-
1	SLIDING DOOR LOWER BRACKET N/S	NOT NECESSARY	299.00	-
1	SLIDING DOOR INNER LOCK N/S	NOT NECESSARY	285.00	-
1	SLIDING DOOR INNER STOPPER N/S	NOT NECESSARY	150.00	-
1	SLIDING DOOR INNER RUBBER N/S	NOT NECESSARY	388.00	-
1	REAR FENDER N/S	TO REPAIR SEE LABOUR	1,979.10	-
1	REAR FENDER LOWER ARCH PANEL N/S	TO REPAIR SEE LABOUR	945.00	-
1	FRONT SHOCK ABSORBER N/S	NOT NECESSARY	320.00	-
1	FRONT KNUCKLE ARM N/S	BENT	1,150.00	672.10
1	FRONT KNUCKLE ARM BEARING N/S	DAMAGED	485.00	425.00
1	FRONT LOWER ARM N/S	NOT NECESSARY	665.10	-
1	FRONT TIE ROD N/S	NOT NECESSARY	125.00	-
1	REAR BUMPER	TO REPAIR SEE LABOUR	752.50	-
	LESS 25% DISCOUNT		-	-1,841.28
			16,326.80	5,523.82

Report Ref No. CC4/LPC23000020/Upa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT DOOR ROC STICKER N/S (SN)	NECESSARY	50.00	30.00
1	SET SLIDING DOOR CORPORATE STICKER N/S (SN)	NECESSARY	800.00	400.00
1	SET REAR FENDER CORPORATE STICKER N/S (SN)	NECESSARY	800.00	300.00
			1,650.00	730.00
	<u>LABOUR</u>			
	TO CHECK WIRING.		50.00	20.00
	TO TRANSFER FRONT DOOR MECHANISM.		80.00	60.00
	TO TRANSFER SLIDING DOOR MECHANISM.		80.00	60.00
	TO CONDUCT WHEEL ALIGNMENT.		120.00	60.00
	TO DISMANTLE & REPLACED FRONT UNDER CARRIAGE.		180.00	120.00
	TO SPRAY RUST PROOFING.		100.00	80.00
	TO DISMANTLE & REFIX FUEL TANK.	NOT NECESSARY	100.00	-
	LABOUR FOR PANEL BEATING & REPLACED PARTS. INCLUSIVE OF THE REPAIR OF FRONT DOOR REAR PILLAR INNER N/S, REAR FENDER N/S, REAR FENDER LOWER ARCH PANEL N/S AND REAR BUMPER.		1,800.00	800.00
	TO PUTTY & SPRAY PAINTING.		1,800.00	1,000.00
			4,310.00	2,200.00
GRAND TOTAL			22,286.80	8,453.82
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,700.00

Report Ref No. CC4/LPC23000020/Upa3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBF 4925A

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBF 4925A

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBF 4925A

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

