NS/INC23000027/Tqp3

REF ASS. RECBY: TEULAN twc: ASSIGNMENT Veh No: SH 6296G. YT Regn: 2017, Oct. From: Date: Estimated lost OD / TP/I WS / TP RES / OD RES / EVA / INV / MV Truck / Trailer or To Inspectivehide No: Make: at Workship m/s Insured / Std / Ni / NA Sp.Reading T/Radio: Insured | Std | NI | NA nsured: Eng/No: Policy No. _____ STDK63F4303:564979 C/No: Claims No. Gen. Cond: Sood / Fair / Poor / Burnt Sum Insued: Excess: Steering: Inofder / Jammed / Leaked / Burnt or (Client's Record) Brake: inprder / Jammed / Leaked / Burnt or Make of Veh: Modi: (Ni) / S/Rim / STD A/Rim or Tyre Size: (Policy Condition) Remark: The veh had commenced its BS | DUN | EXNOVA | GY | FS | LIZA | MIC | DHTSU | PIR | SUMI | repair at the time of inspection. TOYO / YOKO DI Westake Bal. or Warket Value: Front Rear IDAC Accident Roort Consistent? : Yes or No R/Bal. Consistent? : Yes or No GIA / PR Seen: L/Bal L/Bal. 2 days Res.: Yes or No Est. Repairs: D.O.A. D.O.L. Lum Sum: % 3 Val.: Yes or No Survey held at CA / REV / REP. / 24 HRS Des. of Damages: Fit / Rear / O/S / N/S / U/O / Rooftop or Vehicle: IN/OUT Person Contacted: The U/C / Chassis frame / Body Structure affected due to collision. Date / Time | Action / Instruction Taufikh finalised LS \$1200, 2 days. (Red \$1027.43, 46%) Date/Time, File Pass to? : Preli. Report Days Of Repair: 2 : Final Report Resurvey No. of Trip: Survey Fee: Date/Tune, File Return to? Transportation: Add Fee: : Site Insp (\$ S + RS.__SI : Interview (\$ Photos Report Formal: : Tech. Invs (\$ Others Lump Sum / t.B.f. /p 1200 Weellend (\$

F. F. AMMERICA

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO

SH6296G

MAKE

REG 03.10.2017

DATE 20.12.2022

CHIANG INCOME

MODEL TOYOTA PRIUS G4

Qty	Parts Description/ Labour	Туре	Unit Price	Amount	
	REAR BUMPER			Ry \$503.0	
1	REAR BUMPER LOWER COVER			de \$654.9	
1	REAR BUMPER LOWER LH COVER			Ry \$232.0	
1	REAR CENTRE LOWER COVER			× \$148.4	
10	REAR BUMPER CLIP			\$22.0	
	SUB TOTAL			\$1,560.4	
	25.00%			\$390.1	
	DISCOUNTED TOTAL			\$1,170.3	
				,	
1	REAR BUMPER ADVERTISEMENT			\$50.0	
1	BUMPER REVERSE SENSOR			× \$135.7	
				\$172.1	
	Labour Charge				
	Panel Beating			\$525.0	
	Spray Painting Charge			\$300.0	
	Remove/Refix Reverse Sensor			\$60.0	
	TOTAL LABOUR			\$885.0	
	ESTIMATE TOTAL			\$2,227.4	
	5,				
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will				
	be prepared after the vehicle is surveyed by a motor Surveyo				

Taufun 9 44 95749

wp/ 21/12/22 e 415pm

LIS desung after report

-2 days

taufung phants. wn

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Stanature:

Date:



ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Date/Time: 21.12.2022 13:47

Page : 1

Team:

ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5466896

JC NO 305540364

STOMER

I/MS

COMFORT TRANSPORTATION PTE LTD

7010045

STOMER NO. 383 SIN MING DRIVE

Singapore SINGAPORE 575717

65508755

.. (R) (P)

SCOUNT CARD NO.

REGN NO.: 6296G MILEAGE MAKE : TOYOTA E.....F PRIUS HYBRID(G4)21.12.2022 10:50 TARGET DATE

YR OF MANU. 03.10.2017

CHASSIS CODE JTDKB3FU303564979 COMPLETION DATE/TIME:


JOB DESCRIPTION

Accident Date: 20.12.2022 NATURE: 3P 20.12.2022

S/NO

LABOR CODE

DESCRIPTION



CKED & PASSED OUT BY:		
SERVICE ADVISOR	_	CUSTOMER'S SIGNATURE
vledgement Slip	Exit Pass	
	Vehicle No :	

le No.:

Signature/Date

CHIANG

Name of Service Advisor

returned to Service Reception upon collection

SH 6296G

To be kept by Security Guard

SH 6296G