Date: 21/06/2023



 $51\ UBI\ AVE\ 1,\#02-25\ PAYA\ UBI\ INDUSTRIAL\ PARK, SINGAPORE\ 408933\ \ TEL: (065)\ 62563561\ \ FAX: (065)\ 62564315$

Immediate Advice

To: HSBC LIFE (SINGAPORE) PTE. LTD.

Survey Details:

| Date of loss | 30-Dec-2022 | |
|---------------------|---------------------|--|
| Date of appointment | 3-Jan-2023 | |
| Date of survey | 3-Jan-2023 | |
| Location of survey | MG SOLUTION PTE LTD | |

Vehicle Details:

| Claim Type: | THIRD PARTY CLAIM | |
|----------------------|--------------------------|--|
| Vehicle number | GBM258G | |
| Make and Model | TOYOTA HIACE 2.0 DX AUTO | |
| Date of registration | 27-Sep-22 | |
| | | |
| Market Value | \$ 82,000.00 | |
| Parf Rebate | \$ 31,566.00 | |
| Nett Loss | \$ 50,434.00 | |

Repair details:

| Initial Estimate | \$ 7,797.08 |
|------------------|----------------|

Proposed/Revised repair cost:

| Parts | \$ 4,575.80 |
|-------------------------|----------------|
| Check items (estimate) | \$ - |
| Labour | \$ 1,300.00 |
| Total | \$ 5,875.80 |
| Lump Sum(if applicable) | \$ - |

| Number of days for repair | 5.00 | Est. |
|---------------------------|------|------|
|---------------------------|------|------|



 $51\,UBI\,AVE\,1, \#02-25\,PAYA\,UBI\,INDUSTRIAL\,PARK, SINGAPORE\,408933\,\,TEL: (065)\,62563561\,\,FAX: (065)\,62564315$

Remarks:

BASED ON 3RD PARTY VIDEO, IT SHOWS THAT OUR DRIVER WAS MAKING A SUDDEN RIGHT TURN(WITHOUT ANY SIGNAL) AT 2ND LANE AND COLLIDED WITH 3RD PARTY. WE ARE OF THE VIEW THAT LIABILITY IS NOT IN OUR DRIVER'S FAVOUR.

Mandate:

| Liability(TP) | 100% | |
|--------------------------------------|------|----------|
| Proposed repair cost (WITH 8% GST) | \$ | 6,345.86 |
| Loss of use (7 DAYS x \$100.00) | \$ | 700.00 |
| Loss of rental | | NIL |
| Loss of income | | NIL |
| LTA search fees | \$ | 26.75 |
| Others | | NIL |
| Proposed Total | \$ | 7,072.61 |