



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
BLUWEL AUTOMOTIVE SERVICE PTE LTD			Ref:	CS/TP23000029/Uqy3e2
BLK 1 KAKI BUKIT AVE 6			Date:	17/01/2023
#01-28/53/55/56 (MAIN OFFICE)SINGAPORE				
417883				
ON BEHALF OF NAZRULHELMY BIN ABDUL WAHID			Code:	TP149
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.		Veh. Inspected	SJY 4484K	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	03/01/2023	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	VOLKSWAGEN TIGUAN (A)	c.c	1984	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	WVGZZZ5NZBW007528	Colour	WHITE	
Odometer	185518 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	235/40 R19	GOODYEAR	6 mm	
L/H Front Tyre	235/40 R19	GOODYEAR	6 mm	
R/H Rear Tyre	235/40 R19	GOODYEAR	6 mm	
L/H Rear Tyre	235/40 R19	GOODYEAR	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND FRONT WINDSCREEN CRACKED. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	23/12/2022	Inspection Date	03/01/2023	
Survey held at	BLUWEL AUTOMOTIVE SERVICE PL BLK 1 KAKI BUKIT AVE 6 #01-28/53/55/56 (MAIN OFFICE) SINGAPORE 417883			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			7 Working Days	