

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	MSIG INSURANCE	(S) PTE LTD		Ref:	CS3/MSG23000032/y3	
	4 SHENTON WAY SGX CENTRE 2 S	#21-01 INGAPORE 068807		Date:	03/01/2023	
				Code:	MSG	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SLP 4138J	Veh. Inspected		SJM 386A	
	Policy No.	30001961291	Coverage (\$)		0.00	
	Claim No.	297287	Excess (\$)		0.00	
	Assign From	JOWYN TAY	Assign Date		03/01/2023	
2.	2. Vehicle Particulars & Condition					
	Make & Model		c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
	Odometer	-	Steering			
	Brakes		Modification			
	General					
3.	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
4.		Description of Damages				
5.	General Information					
	Accident Date	29/12/2022	Inspection Date	е		
	Survey held at	1 Bukit Batok Cresent, #05-55 W	NCEGA Plaza, 658064			
	Repairer	GARAGE B PTE LTD	PTE LTD			
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					