

**Auto Insure Pte Ltd (HQ)** (Co.Reg.No:201437380M)6 Marsiling Lane  
Singapore 739145

Tel: 3157 2626 Fax: 6368 0081 Email: claims@autoinsure.com.sg

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2001690369-01	Date of Loss:	26/12/2022
Vehicle Reg. No.:	<b>SMM6700B</b>	Driveable?	
Driver Age/Info:	/ MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	JISMI BIN MOHAMMAD		
Driver:	JISMI BIN MOHAMMAD		

Make/Model:	MITSUBISHI OUTLANDER, 2.4 CVT 4WD (A)	Vehicle Reg. Date:	25/05/2017
Vehicle Colour:	BROWN		
Engine No:	4B12SX8885	Chassis No:	JMYXTGF3WHJ000925
Odometer:	73510 KM		

Paint Type:	
Total Loss?	<b>NO</b>
Est. Duration of Repair (day)	7

Present Location: AUTO INSURE PTE LTD (HQ) (WOODLANDS)

**COST OF CLAIMS**

	<b>Amount</b>
Parts	4,290.00
Miscellaneous Items	85.00
Labour	1,000.00
Paintwork Labour	1,000.00
Towing	0.00
	<b>Gross Total (\$\$)</b>
	<b>6,375.00</b>
	<b>+ GST 7.00% (\$\$)</b>
	446.25
	<b>Nett Amount (\$\$)</b>
	<b>6,821.25</b>

**This claim is handled by: LOH CHEN KHUAN**

Generated using Merimen e-Claims Internet Estimation &amp; Adjusting System

**REPAIR DETAILS****Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 30 Dec 2022)**Parts:** M1-SUV MITSUBISHI OUTLANDER 2.4 CVT 4WD (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Auto Insure Pte Ltd (HQ)/SMM6700B/30/12/2022 15:13**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER	0.00	0.00	*660.00 F
2	1		*FRONT BUMPER SIDE RETAINER LH	0.00	0.00	*20.00 F
3	1		*HEAD LAMP LH	0.00	0.00	*660.00 F
4	1		*FOG LAMP COVER LH	0.00	0.00	*55.00 F
5	1		*FRONT FENDER LH	0.00	0.00	*460.00 F
6	1		*FOG LAMP CHROME MOULDING LH	0.00	0.00	*80.00 F
7	1		*FRONT BUMPER CHROME MOULDING LH	0.00	0.00	*145.00 F
8	1		*FRONT BUMPER CENTER COVER	0.00	0.00	*240.00 F
9	1		*RADIATOR TOP COVER	0.00	0.00	*50.00 F
10	1		*FRONT GRILLE	0.00	0.00	*400.00 F
11	1		*FRONT BONNET	0.00	0.00	*720.00 F
12	1		*FRONT BUMPER REINFORCEMENT	0.00	0.00	*410.00 F

F=Franchise part.

<b>Sub Total (\$)</b>	<b>3,900.00</b>
<b>+ Margin on L,N Items 10.00% (\$)</b>	<b>390.00</b>
<b>Total Parts (\$)</b>	<b>4,290.00</b>

Auto Insure Pte Ltd (HQ)/SMM6700B/30/12/2022 15:13. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<b>Miscellaneous Items</b>			
1	1	FRONT BUMPER CLIPS	50.00
2	1	FRONT NUMBER PLATE WITH HOLDER	35.00
<b>Sub Total (S\$)</b>			<b>85.00</b>

## Estimates on Labour

No	Particulars	Lab.Type	Amount
<b>Paintwork Labour</b>			
1	LABOUR FOR SPRAY PAINTING	New	1,000.00
<b>Labour Items</b>			
2	LABOUR FOR PANEL BEATING	New	1,000.00
<b>Gross Labour Cost (S\$)</b>			<b>2,000.00</b>

Auto Insure Pte Ltd (HQ)/SMM6700B/30/12/2022 15:13. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

**< END OF ESTIMATES >**