

Auto Insure Pte Ltd (HQ) (Co.Reg.No:201437380M)

6 Marsiling Lane
Singapore 739145

Tel: 3157 2626 Fax: 6368 0081 Email: claims@autoinsure.com.sg

INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2001690369-01	Date of Loss:	26/12/2022
Vehicle Reg. No.:	SMM6700B	Driveable?	
Driver Age/Info:	/ MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	JISMI BIN MOHAMMAD		
Driver:	JISMI BIN MOHAMMAD		
Make/Model:	MITSUBISHI OUTLANDER, 2.4 CVT 4WD (A)	Vehicle Reg. Date:	25/05/2017
Vehicle Colour:	BROWN		
Engine No:	4B12SX8885	Chassis No:	JMYXTGF3WHJ000925
Odometer:	73510 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	7		
Present Location:	AUTO INSURE PTE LTD (HQ) (WOODLANDS)		

COST OF CLAIMS

	Amount
Parts	4,290.00
Miscellaneous Items	85.00
Labour	1,000.00
Paintwork Labour	1,000.00
Towing	0.00
Gross Total (S\$)	6,375.00
+ GST 7.00% (S\$)	446.25
Nett Amount (S\$)	6,821.25

his claim is handled by: LOH CHEN KHUAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

2991

4533.10

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 30 Dec 2022)

Parts: M1-SUV MITSUBISHI OUTLANDER 2.4 CVT 4WD (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Auto Insure Pte Ltd (HQ)/SMM6700B/30/12/2022 15:13

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER	0.00	0.00	de ✓ *660.00 F ✓
2	1		*FRONT BUMPER SIDE RETAINER LH	nn 0.00	0.00	de ✓ *20.00 F ✗
3	1		*HEAD LAMP LH	over ✓ 0.00	0.00	? *660.00 F ✓
4	1		*FOG LAMP COVER LH	nn 0.00	0.00	mi ✓ *55.00 F ✗
5	1		*FRONT FENDER LH	0.00	0.00	RY *460.00 F ✓
6	1		*FOG LAMP CHROME MOULDING LH	cut 0.00	0.00	? *80.00 F ✓
7	1		*FRONT BUMPER CHROME MOULDING LH	0.00	0.00	mi ✓ *145.00 F ✓
8	1		*FRONT BUMPER CENTER COVER	0.00	0.00	mi ✓ *240.00 F ✓
9	1		*RADIATOR TOP COVER	0.00	0.00	bu ✓ *50.00 F ✓
10	1		*FRONT GRILLE	over ✓ 0.00	0.00	? *400.00 F ✓
11	1		*FRONT BONNET	0.00	0.00	RY *720.00 F ✓
12	1		*FRONT BUMPER REINFORCEMENT	0.00	0.00	? *410.00 F ✓

F=Franchise part.

Sub Total (S\$)	3,900.00
+ Margin on L,N Items 10.00% (S\$)	390.00
Total Parts (S\$)	4,290.00

Auto Insure Pte Ltd (HQ)/SMM6700B/30/12/2022 15:13. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	FRONT BUMPER CLIPS	30mc 50.00
2	1	FRONT NUMBER PLATE WITH HOLDER	crn 35.00
Sub Total (\$\$)			85.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	LABOUR FOR SPRAY PAINTING	New	600 1,000.00
<u>Labour Items</u>			
2	LABOUR FOR PANEL BEATING	New	600 1,000.00
Gross Labour Cost (\$\$)			2,000.00

Auto Insure Pte Ltd (HQ)/SMM6700B/30/12/2022 15:13. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tanfui 97475749
3/2/23
Not Approve
Ex \$600
tanfui@lhauto.com
4-5 days.

P/P Reming before paint
* No 2nd hand parts

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



Auto Insure Pte. Ltd.
6 Marsiling Lane
Singapore (739145)
E: claims01@autoinsure.com.sg
W: www.autoinsure.com.sg
T: 3157 2626 F: 6368 0081
GST No.: 201437380M

SUPPLEMENTARY ITEMS

Our Ref: SMM6700B

S/NO	QTY	DESCRIPTIONS	ASSESSED CONDITION	EST. BY WORKSHOP
		<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	1	FR BPR BEAM UPP REINF		\$ 96.00
2	1	HEADLAMP RH		\$ 690.00
			SUB TOTAL	\$ 786.00
			MARGIN 10%	\$ 78.60
			TOTAL AMOUNT	\$ 864.60

bt ✓
mq ✓