

**Auto Insure Pte Ltd (HQ)** (Co.Reg.No:201437380M)6 Marsiling Lane  
Singapore 739145

Tel: 3157 2626 Fax: 6368 0081 Email: claims@autoinsure.com.sg

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2001690369-01	Date of Loss:	26/12/2022
Vehicle Reg. No.:	<b>SMM6700B</b>	Driveable?	
Driver Age/Info:	/ MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	JISMI BIN MOHAMMAD		
Driver:	JISMI BIN MOHAMMAD		

Make/Model:	MITSUBISHI OUTLANDER, 2.4 CVT 4WD (A)	Vehicle Reg. Date:	25/05/2017
Vehicle Colour:	BROWN		
Engine No:	4B12SX8885	Chassis No:	JMYXTGF3WHJ000925
Odometer:	73510 KM		

Paint Type:	
Total Loss?	<b>NO</b>
Est. Duration of Repair (day)	7

Present Location: **AUTO INSURE PTE LTD (HQ) (WOODLANDS)****COST OF CLAIMS**

	<b>Amount</b>
Parts	4,290.00
Miscellaneous Items	85.00
Labour	1,000.00
Paintwork Labour	1,000.00
Towing	0.00
<b>Gross Total (S\$)</b>	<b>6,375.00</b>
<b>+ GST 7.00% (S\$)</b>	<b>446.25</b>
<b>Nett Amount (S\$)</b>	<b>6,821.25</b>

**This claim is handled by: LOH CHEN KHUAN**Generated using *Merimen e-Claims Internet Estimation & Adjusting System*

**REPAIR DETAILS****Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 30 Dec 2022)

Parts: M1-SUV MITSUBISHI OUTLANDER 2.4 CVT 4WD (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Auto Insure Pte Ltd (HQ)/SMM6700B/30/12/2022 15:13

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER	0.00	0.00	de ✓ *660.00 F
2	1		*FRONT BUMPER SIDE RETAINER LH	0.00	0.00	de ✓ *20.00 F
3	1		*HEAD LAMP LH	0.00	0.00	? *660.00 F
4	1		*FOG LAMP COVER LH	0.00	0.00	mis ✓ *55.00 F
5	1		*FRONT FENDER LH	0.00	0.00	Ry ✓ *460.00 F
6	1		*FOG LAMP CHROME MOULDING LH	0.00	0.00	? *80.00 F
7	1		*FRONT BUMPER CHROME MOULDING LH	0.00	0.00	ma ✓ *145.00 F
8	1		*FRONT BUMPER CENTER COVER	0.00	0.00	ma ✓ *240.00 F
9	1		*RADIATOR TOP COVER	0.00	0.00	? *50.00 F
10	1		*FRONT GRILLE	0.00	0.00	? *400.00 F
11	1		*FRONT BONNET	0.00	0.00	Ry ✓ *720.00 F
12	1		*FRONT BUMPER REINFORCEMENT	0.00	0.00	? *410.00 F

F=Franchise part.

<b>Sub Total (S\$)</b>	<b>3,900.00</b>
<b>+ Margin on L,N Items 10.00% (S\$)</b>	<b>390.00</b>
<b>Total Parts (S\$)</b>	<b>4,290.00</b>

Auto Insure Pte Ltd (HQ)/SMM6700B/30/12/2022 15:13. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

### Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<b>Miscellaneous Items</b>			
1	1	FRONT BUMPER CLIPS	30ml 50.00
2	1	FRONT NUMBER PLATE WITH HOLDER	35.00
<b>Sub Total (\$\$)</b>			<b>85.00</b>

### Estimates on Labour

No	Particulars	Lab.Type	Amount
<b>Paintwork Labour</b>			
1	LABOUR FOR SPRAY PAINTING	New	600 1,000.00
<b>Labour Items</b>			
2	LABOUR FOR PANEL BEATING	New	600 1,000.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,000.00</b>

Auto Insure Pte Ltd (HQ)/SMM6700B/30/12/2022 15:13. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tanjim 97475749  
3/2/23  
Not Antwise  
Ex \$600  
tanjim@lhauto.com  
4-5 days.

P/P Remy before paint  
# No 2nd hand parts

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: