

Section A - Accident Details

Registration Number	SHB1076U
Case Reference Number	TAX/01/23/2001
Registration Date	26/Dec/2019
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4FL
Name of Driver	NG KENG SIAH
Type of Accident	Head To Side
Accident Date and Time	2/Jan/2023 11:41 PM
Accident Reported Date and Time	3/Jan/2023 9:15 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24117279
Special Instruction to ARC, if any	LEFT PORTION/ CHINA TAIPING - LKK
Prepared Date and Time	3/Jan/2023 10:36 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,602.00	\$750.00
Total Spray Cost	\$2,952.00	\$1,140.00
Total Spare Part Cost	\$7,634.50	\$2,659.51
Total Other Cost	\$620.00	\$230.00
TOTAL COST	\$12,808.50	\$4,779.51
Lump Sum Total	\$12,800.00	\$4,800.00 (L/S)
Number of Repair Days	10.0	5.0
Prepared / Adjusted By	Boon Chew Tay	Kenneth Kong (LKK) / China Taiping
ARC / Surveyor Sign Off Date	04/01/2023 5:13 PM	04/01/2023 5:08 PM
Signature		
Remarks	Initial 8 days / sup 2 days / total 10 days	LUMPSUM REPAIR / AFTER PAINT PHOTOS, FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR Kenneth Kong HP/97888708 & KennethKong@lkkauto.com>

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2301-0373	Invoice Number	
Quotation Date	31.01.2023	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works		
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR LH PORTION	\$1,352.00	\$600.00
TO REPAIR CENTRE PILLAR	\$250.00	\$150.00
Total Labour	\$1,602.00	\$750.00

Part 2 - Spray Painting & Panel Beating Related Works		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00
TO RESPRAY APRON PANEL LH	\$180.00	\$0.00
TO RESPRAY FRONT PILLAR LH	\$180.00	\$0.00
TO RESPRAY FRONT DOOR LH	\$378.00	\$200.00
TO RESPRAY VIEW MIRROR	\$180.00	\$50.00
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$150.00
TO RESPRAY SILL MEMBER LH	\$180.00	\$0.00
TO RESRAY REAR DOOR LH	\$378.00	\$200.00
TO RESPRAY CENTRE PILLAR LH	\$180.00	\$0.00
TO RESPRAY DOOR HANDLE	\$180.00	\$40.00
TO RESPRAY CENTRE PILLAR LH	\$180.00	\$150.00
TO RESPRAY REAR FENDER LH	\$378.00	\$150.00
Total Spray Painting & Panel Beating	\$2,952.00	\$1,140.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO WASH AND VACUUM	\$60.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$90.00
TO TRANSFER DOOR MECHANISM	\$240.00	\$120.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Total Other Costs	\$620.00	\$230.00

Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		53802-47100	FENDER SUB-ASSY, FR , LH	1.00	\$1,060.70	25.00	\$795.53	Replace	Replace
		75374-47140	EMBLEM, SIDE PANEL (HYBRID)	1.00	\$59.10	25.00	\$44.33	Replace	Replace
		53876-47060	LINER, FR FENDER, LH	0.00	\$227.80	0.00	\$0.00	Replace	Not Given

√ bt
√ nec
X svc

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 14/02/2023

User ID : PohSuan

		53857-12010	RETAINER, FR WHEEL RH	0.00	\$3.50	0.00	\$0.00	Replace	Not Given	X	
		53828-47070	PROTECTOR, FR FENDER LH	0.00	\$101.80	0.00	\$0.00	Replace	Not Given	X	
		53852-47041	PAD, FR WHEEL LH	0.00	\$65.00	0.00	\$0.00	Replace	Not Given	X	
		53702-47101	APRON SUB-ASSY, FRONT FENDER , LH	0.00	\$1,060.90	0.00	\$0.00	Replace	Not Given	X	
		61014-47020	PILLAR, FRONT BODY, LH	0.00	\$378.90	0.00	\$0.00	Replace	Not Given	X	
		87945-47060-A1	COVER, OUTER MIRROR, LH	0.00	\$117.80	0.00	\$0.00	Replace	Check	X	
		75860-47900	MOULDING ASSY, BODY ROCKER PANEL , LH	1.00	\$649.10	100.00	\$0.00	Replace	Repair	R	
		61312-47040	PILLAR, CENTER BODY, OUTER LH	0.00	\$349.50	0.00	\$0.00	Replace	Not Given	X	r
		67002-47163	PANEL SUB-ASSY, FRONT DOOR LH	1.00	\$1,407.80	25.00	\$1,055.85	Replace	Replace	√	bt
		68610-47040	CHECK ASSY, FRONT DOOR	0.00	\$199.40	0.00	\$0.00	Replace	Not Given	X	
		67862-47060	WEATHERSTRIP, FRONT DOOR LH	0.00	\$250.70	0.00	\$0.00	Replace	Check	X	
		69040-47100	LOCK ASSY, FRONT DOOR LH	0.00	\$607.90	0.00	\$0.00	Replace	Not Given	X	r
		69410-20110	DOOR LOCK STRIKER	0.00	\$42.60	0.00	\$0.00	Replace	Not Given	X	s
		69210-47051-A1	DOOR OUTER HANDLE FRONT , LH	1.00	\$423.20	25.00	\$317.40	Replace	Replace	√	dd
		68720-12151	HINGE ASSY, FRONT DOOR , UPPER LH	0.00	\$105.50	0.00	\$0.00	Replace	Check	X	
		68740-12120	HINGE ASSY, FRONT DOOR , LOWER LH	0.00	\$120.00	0.00	\$0.00	Replace	Check	X	
		69802-21010	DOOR FRONT WINDOW REGULATOR SUB-ASSY, LH	0.00	\$257.80	0.00	\$0.00	Replace	Check	X	
		85720-47140	DOOR FRONT MOTOR ASSY, POWER WINDOW	0.00	\$996.60	0.00	\$0.00	Replace	Check	X	
			STICKER STRIDES TAXI (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace	√	nec
		82152-47870	WIRE, FRONT DOOR, LH	0.00	\$513.50	0.00	\$0.00	Replace	Not Given	X	svc
		67004-47211	PANEL SUB-ASSY, REAR DOOR , LH	1.00	\$1,401.70	25.00	\$1,051.28	Replace	Replace	√	br
		68630-47050	CHECK ASSY, REAR DOOR	0.00	\$199.40	0.00	\$0.00	Replace	Not Given	X	svc
		68760-20122	HINGE ASSY, REAR DOOR , UPPER LH	0.00	\$107.00	0.00	\$0.00	Replace	Not Given	X	
		68780-52031	HINGE ASSY, REAR DOOR , LOWER LH	0.00	\$93.90	0.00	\$0.00	Replace	Not Given	X	
		85710-47150	DOOR REAR MOTOR ASSY, POWER WINDOW	0.00	\$996.60	0.00	\$0.00	Replace	Not Given	X	
		69804-47020	DOOR REAR WINDOW REGULATOR SUB-ASSY, LH	0.00	\$223.50	0.00	\$0.00	Replace	Not Given	X	
Total					\$12,081.20		\$3,324.39				

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

	3,324.39	
	-20%	
	<u>2659.51</u>	L/S \$4,800/-
+	750.00	
+	<u>1370.00</u>	
	4,779.51	