



FALCON-AIR

LONPAC INSURANCE BHD
300 BEACH ROAD #17-04/07
THE CONCOURSE 199555
ATTENTION: GERALD POH
Attention: Motor Claim Department
Contact: 62507388 Fax No.: 62962706

FALCON-AIR AUTO SERVICES PTE LTD

Co. Reg. No.: 199501140D
GST Reg. No.: 199501140D

Not Authorized
6 days &
Mummy After Paint
B4
Ex 8500

7 days

Estimate: ES012549

Date: 03/01/2023
Vehicle Num.: SLK 710J
Make/Model: HONDA STEPWGN SPADA-2016/2017
Chassis/Eng#: RP31100595
Accident Date: 23/12/2022
Claim No.:
Reference: O/D
Policy No.: Z22VP05030366

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

PARTS PURCHASED :				
1.	1 PC	FRONT WINDSCREEN GLASS		
2.	1 PC	FRONT WINDSCREEN GLASS MOULDING		
3.	1 PC	LH FRONT WIPER PANEL GARNISH		
4.	1 PC	BONNET		
5.	2 PCS	BONNET HINGE		
6.	1 PC	BONNET LOCK		
7.	1 PC	RH FRONT FENDER		
8.	1 PC	LH FRONT FENDER		
9.	1 PC	AIR DUCT		
10.	1 PC	RADIATOR SUPPORT PANEL		
11.	1 PC	RADIATOR		
12.	1 PC	RADIATOR FAN COWLING		
13.	1 PC	RADIATOR FAN BLADE		
14.	1 PC	RADIATOR FAN MOTOR		
15.	1 PC	AIR CON CONDENSER		
16.	1 PC	AIR CON FAN COWLING		
17.	1 PC	AIR CON FAN BLADE		
18.	1 PC	AIR CON FAN MOTOR		
19.	1 PC	LH HEADLAMP		
20.	1 PC	LH HEADLAMP LOWER BRACKET		
21.	2 PCS	RADIATOR TOP MOUNTING		
22.	1 PC	RH HEADLAMP		

CM	1,250.00	✓
MA	30.00	✓
PA	25.00	✓
PA	550.00	✓
PA	40.00	✓
PA	80.00	✓
PA	90.00	✓
PA	420.00	X
PA	420.00	✓
PA	70.00	?
PA	450.00	✓
PA	880.00	✓
PA	95.00	?
PA	65.00	?
PA	235.00	?
PA	750.00	✓
PA	75.00	?
PA	60.00	?
PA	185.00	?
PA	1,200.00	✓
PA	50.00	?
PA	20.00	✓
PA	40.00	X
PA	1,200.00	✓

CONTINUE / ...

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FALCON-AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop (Blk 1/Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110
Website: www.falconair.com.sg Email: email@falconair.com.sg



FALCON-AIR

LONPAC INSURANCE BHD
300 BEACH ROAD #17-04/07
THE CONCOURSE 199555
ATTENTION: GERALD POH

Attention : Motor Claim Department

Contact : 62507388 Fax No. : 62962706

Page 2 / 3
FALCON - AIR AUTO SERVICES PTE LTD
Co Reg No : 199501140D
GST Reg No : 199501140D

Estimate : ES012549

Date : 03/01/2023
Vehicle Num : SLK 710J
Make/Model : HONDA STEPWGN SPADA-2016/2017
Chassis/Eng# : RP31100595
Accident Date : 23/12/2022
Claim No :
Reference : O/D
Policy No : Z22VP05030366

S/N	Quantity	Particular	Unit Price	Amount S\$
23.	1 PC	RH HEADLAMP LOWER BRACKET	CM 50.00	✓
24.	1 PC	RADAR BRACKET	108.00	✓
25.	1 PC	RADAR ASSY	2,100.00	✓
26.	1 PC	RADAR HOLDER	CM 320.00	✓
27.	1 PC	FRONT GRILLE BASE	CM 165.00	✓
28.	2 PCS	FRONT GRILLE CLIP	6.00 12.00	✓
29.	1 PC	FRONT GRILLE HOLDER	CM 25.00	x
30.	1 PC	FRONT GRILLE TOP COVER	BU 50.00	✓
31.	1 PC	FRONT GRILLE LOGO	21.00	✓
32.	1 PC	FRONT GRILLE CHROME	CM 520.00	✓
33.	1 PC	FRONT GRILLE CHROME	CM 120.00	✓
34.	1 PC	FRONT BUMPER	BU 550.00	✓
35.	1 PC	FRONT BUMPER REINFORCEMENT	BU 255.00	✓
36.	1 PC	FRONT BUMPER LOWER GRILLE	CM 8.00	✓
37.	1 PC	FRONT BUMPER LOWER CHROME	CM 180.00	✓
38.	2 PCS	FOG LAMP GARNISH	80.00 160.00	✓
39.	1 PC	FRONT BUMPER LOWER COVER	BU 115.00	x
40.	2 PCS	FRONT BUMPER SIDE RETAINER TOP	75.00 150.00	✓
41.	2 PCS	FRONT BUMPER SIDE RETAINER LOWER	45.00 90.00	✓
42.	1 PC	RH FRONT FENDER UNDERSHIELD	CM 95.00	✓
43.	1 PC	INTERCOOLER	PU 2,000.00	✓
44.	1 PC	BATTERY BOX GARNISH	50.00	✓
45.	1 PC	FRONT GRILLE REFLECTOR	CM 330.00	✓
46.	1 PC	FRONT GRILLE LOWER	CM 170.00	✓

Total Parts Purchased S\$:

15,864.00

15.00% Of The Above Parts S\$:

2,379.60

Based On Cost Plus S\$:

18,243.60

CONTINUE / ...



FALCON - AIR

LONPAC INSURANCE BHD
300 BEACH ROAD #17-04/07
THE CONOURSE 199555
ATTENTION: GERALD POH

Attention : Motor Claim Department
Contact : 62507388 Fax No. : 62962706

FALCON - AIR AUTO SERVICES PTE LTD
Page 3/3
Co. Reg. No. : 199501140D
GST Reg. No. : 199501140D

Estimate : ES012549

Date : 03/01/2023
Vehicle Num. : SLK 710J
Make/Model : HONDA STEPWGN SPADA-2016/2017
Chassis/Eng# : RP31100595
Accident Date : 23/12/2022
Claim No. :
Reference : O/D
Policy No. : Z22VP05030366

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

- | | | |
|----|-------|-------------------------------|
| 1. | 1 PC | SPECIAL NETT ITEMS : |
| 2. | 1 PC | WINDSCREEN GLASS SEALANT |
| 3. | 1 SET | IU BRACKET |
| 4. | 1 PC | RADIATOR SUPPORT GARNISH CLIP |
| 5. | 1 SET | FRONT NUMBER PLATE |
| 6. | 1 PC | FRONT BUMPER CLIP |
| 7. | 1 PC | FRONT FENDER SHIELD CLIP |
| | | FRONT GRILLE CLIP |

Special Nett Total S\$:

LABOUR :

TO CHECK WIRING AND LIGHT SYSTEM

TO VACUUM, RE-OIL AND RE-GAS AIR CON

TO REMOVE/REFIX FRONT WINDSCREEN GLASS

TO COMPUTER RESET RADAR AND ELECTRONIC FUNCTION

TO CUT OUT/REWELD RADIATOR SUPPORT PANEL, STRAIGHTEN

FRONT CHASSIS, INNER PANEL, LH FRONT WHEEL HOUSE

INCLUDING REPLACEMENT OF PARTS

TO SPRAY PAINT BONNET, RADIATOR SUPPORT PANEL, FRONT

BUMPER, FRONT REINFORCEMENT, LH FRONT FENDER, RH FRONT

FENDER, LH FRONT WHEEL HOUSE

Labour Total S\$:

40.00	—
26.00	—
60.00	—
45.00	—
60.00	—
50.00	—
50.00	—

331.00

50.00	202
120.00	1001
120.00	—
250.00	7

1,000.00 704

1,600.00 1000

3,140.00

E. & O.E.

Total S\$: 21,714.60

for FALCON AIR AUTO SERVICES PTE LTD

The quotation was prepared from visual inspection. Further materials and labour charges may be required when repair commences. We will advise you accordingly.