



FALCON-AIR

FALCON - AIR AUTO SERVICES PTE LTD

Co. Reg. No.: 199501140D
GST Reg. No.: 199501140DLONPAC INSURANCE BHD
300 BEACH ROAD #17-04/07
THE CONCOURSE 199555
ATTENTION: GERALD POH

Attention : Motor Claim Department

Contact : 62507388 Fax No. : 62962706

Estimate : ES012549

Date : 03/01/2023

Vehicle Num. : SLK 710J

Make/Model : HONDA STEPWGN SPADA-2016/2017

Chassis/Eng# : RP31100595

Accident Date : 23/12/2022

Claim No. :

Reference : O/D

Policy No. : Z22VP05030366

S/N	Quantity	Particular	Unit Price	Amount S\$
PARTS PURCHASED :				
1.	1 PC	FRONT WINDSCREEN GLASS		1,250.00
2.	1 PC	FRONT WINDSCREEN GLASS MOULDING		30.00
3.	1 PC	LH FRONT WIPER PANEL GARNISH		25.00
4.	1 PC	BONNET		550.00
5.	2 PCS	BONNET HINGE	40.00	80.00
6.	1 PC	BONNET LOCK		90.00
7.	1 PC	RH FRONT FENDER		420.00
8.	1 PC	LH FRONT FENDER		420.00
9.	1 PC	AIR DUCT		70.00
10.	1 PC	RADIATOR SUPPORT PANEL		450.00
11.	1 PC	RADIATOR		880.00
12.	1 PC	RADIATOR FAN COWLING		95.00
13.	1 PC	RADIATOR FAN BLADE		65.00
14.	1 PC	RADIATOR FAN MOTOR		235.00
15.	1 PC	AIR CON CONDENSER		750.00
16.	1 PC	AIR CON FAN COWLING		75.00
17.	1 PC	AIR CON FAN BLADE		60.00
18.	1 PC	AIR CON FAN MOTOR		185.00
19.	1 PC	LH HEADLAMP		1,200.00
20.	1 PC	LH HEADLAMP LOWER BRACKET		50.00
21.	2 PCS	RADIATOR TOP MOUNTING	20.00	40.00
22.	1 PC	RH HEADLAMP		1,200.00

CONTINUE / ...

FALCON - AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862

Branches : Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop (Blk 1/Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110
Website: www.falconair.com.sg Email: email@falconair.com.sg



FALCON - AIR

FALCON - AIR AUTO SERVICES PTE LTD

Co. Reg. No.: 199501140D
GST Reg. No.: 199501140DLONPAC INSURANCE BHD
300 BEACH ROAD #17-04/07
THE CONCOURSE 199555
ATTENTION: GERALD POH

Attention : Motor Claim Department

Contact : 62507388 Fax No. : 62962706

Estimate : ES012549

Date : 03/01/2023

Vehicle Num. : SLK 710J

Make/Model : HONDA STEPWGN SPADA-2016/2017

Chassis/Eng# : RP31100595

Accident Date : 23/12/2022

Claim No. :

Reference : O/D

Policy No. : Z22VP05030366

S/N	Quantity	Particular	Unit Price	Amount S\$
23.	1 PC	RH HEADLAMP LOWER BRACKET		50.00
24.	1 PC	RADAR BRACKET		108.00
25.	1 PC	RADAR ASSY		2,100.00
26.	1 PC	RADAR HOLDER		320.00
27.	1 PC	FRONT GRILLE BASE		165.00
28.	2 PCS	FRONT GRILLE CLIP	6.00	12.00
29.	1 PC	FRONT GRILLE HOLDER		25.00
30.	1 PC	FRONT GRILLE TOP COVER		50.00
31.	1 PC	FRONT GRILLE LOGO		21.00
32.	1 PC	FRONT GRILLE CHROME		520.00
33.	1 PC	FRONT GRILLE CHROME		120.00
34.	1 PC	FRONT BUMPER		550.00
35.	1 PC	FRONT BUMPER REINFORCEMENT		255.00
36.	1 PC	FRONT BUMPER LOWER GRILLE		8.00
37.	1 PC	FRONT BUMPER LOWER CHROME		180.00
38.	2 PCS	FOG LAMP GARNISH	80.00	160.00
39.	1 PC	FRONT BUMPER LOWER COVER		115.00
40.	2 PCS	FRONT BUMPER SIDE RETAINER TOP	75.00	150.00
41.	2 PCS	FRONT BUMPER SIDE RETAINER LOWER	45.00	90.00
42.	1 PC	RH FRONT FENDER UNDERSHIELD		95.00
43.	1 PC	INTERCOOLER		2,000.00
44.	1 PC	BATTERY BOX GARNISH		50.00
45.	1 PC	FRONT GRILLE REFLECTOR		330.00
46.	1 PC	FRONT GRILLE LOWER		170.00
Total Parts Purchased S\$:				15,864.00
15.00% Of The Above Parts S\$:				2,379.60
Based On Cost Plus S\$:				18,243.60

CONTINUE / ...



FALCON - AIR

LONPAC INSURANCE BHD
300 BEACH ROAD #17-04/07
THE CONCOURSE 199555
ATTENTION: GERALD POH

Attention : Motor Claim Department

Contact : 62507388 Fax No. : 62962706

FALCON - AIR AUTO SERVICES PTE LTD

Co. Reg. No.: 199501140D
GST Reg. No.: 199501140D

Page 3 / 3

Estimate : ES012549

Date : 03/01/2023
Vehicle Num. : SLK 710J
Make/Model : HONDA STEPWGN SPADA-2016/2017
Chassis/Eng# : RP31100595
Accident Date : 23/12/22
Claim No. :
Reference : O/D
Policy No. : Z22VP05030366

S/N	Quantity	Particular	Unit Price	Amount S\$
SPECIAL NETT ITEMS :				
1.	1 PC	WINDSCREEN GLASS SEALANT		40.00
2.	1 PC	IU BRACKET		26.00
3.	1 SET	RADIATOR SUPPORT GARNISH CLIP		60.00
4.	1 PC	FRONT NUMBER PLATE		45.00
5.	1 SET	FRONT BUMPER CLIP		60.00
6.	1 PC	FRONT FENDER SHIELD CLIP		50.00
7.	1 PC	FRONT GRILLE CLIP		50.00
Special Nett Total S\$:				331.00
LABOUR :				
TO CHECK WIRING AND LIGHT SYSTEM				50.00
TO VACUUM, RE-OIL AND RE-GAS AIR CON				120.00
TO REMOVE/REFIX FRONT WINDSCREEN GLASS				120.00
TO COMPUTER RESET RADAR AND ELECTRONIC FUNCTION				250.00
TO CUT OUT/REWELD RADIATOR SUPPORT PANEL, STRAIGHTEN FRONT CHASSIS, INNER PANEL, LH FRONT WHEEL HOUSE INCLUDING REPLACEMENT OF PARTS				1,000.00
TO SPRAY PAINT BONNET, RADIATOR SUPPORT PANEL, FRONT BUMPER, FRONT REINFORCEMENT, LH FRONT FENDER, RH FRONT FENDER, LH FRONT WHEEL HOUSE				1,600.00
Labour Total S\$:				3,140.00
E. & O.E.			Total S\$:	21,714.60

for FALCON AIR AUTO SERVICES PTE LTD

The quotation was prepared from visual inspection. Further materials and labour charges may be required when repair commences. We will advise you accordingly.

FALCON - AIR AUTO SERVICES PTE LTD
[a subsidiary of Falcon-Air Holdings Pte Ltd]

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862

Branches : Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop (Blk 1/Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110
Website: www.falconair.com.sg Email: email@falconair.com.sg