



南方摩哆

Southern Motor

Business Reg. No: 234147/00L

Block 1006, Bukit Merah Lane 2. #01-10, Singapore 159762

Tel: 6273-0369 (3 Lines) Fax: 6274-6614

23 December 2022

RE: Cost of repair to Yamaha Aerox - FBT792T

1pc of Front Fairing Bracket ?		SS	110.00
1pc of Body Set <i>scm</i>	<i>2 case</i>		480.00
1pc of Footrest Plate Comp <i>cm</i>			240.00
1pc of Mirror <i>scm</i>	<i>HP 90000068</i>		75.00
1pc of Handle Bar ?			110.00
1pc of Handle Grip <i>cut</i>	<i>6 days</i>		25.00
1pc of Front Fork <i>bt</i>	<i>4/5 or p/p?</i>		480.00
1pc of Steering Cone Stand ?			250.00
1pc of Front Sport Rim <i>repair</i>			240.00
1pc of Front Brake Disk ?			120.00
1pc of Front Rim Sub ?			40.00
1pc of Lower Cowling <i>cm</i>	<i>04/01/23 @ 1230</i>		120.00
1pc of Front Body Cover <i>scm</i>			230.00
1pc of Air Box Cover <i>scm</i>	<i>Resy after or before part</i>		95.00
1pc of Belt Cover <i>cm</i>			160.00
1pc of Rear Sport Rim ?			245.00
1pc of Rear Tyre <i>scm</i>			140.00
1pc of Rear Fork <i>H</i>			220.00
1pc of Rear Mudguard <i>cm</i>			160.00
1pc of Tail Light ?			140.00
1pc of Exhaust Pipe <i>bt</i>			480.00
1pc of Rear Box Bracket <i>bt</i>			160.00
1pc of Rear Givi Box <i>mis</i>			250.00
1pc of Exhaust Pipe Bracket <i>cm</i>			220.00
1pc of Rear Number Plate Light <i>cut</i>			60.00
1pc of Tail Cover <i>cut</i>			120.00
1pc of Handle Balancer Set <i>mis</i>			30.00
1pc of Seat <i>cut</i>			235.00
1pc of Rear Footrest <i>scm</i>			45.00

5,280.00

Less 10%

528.00

Nett

4,752.00

Transport

40.00

Jack Body & Alignment Front & Rear

500.00

Number Plate

15.00

Steering Cone

90.00

Labour

650.00

\$6,047.00

Main stand scm \$75

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

Yours Faithfully,
Southern Motor

receipt?
~~420~~ 350
bt
20 m
450