

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: ECICS Limited
10 Eunos Road 8
#09-04A Singapore Post Centre
Singapore 408600From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 12 Apr 2023

Preliminary Advice

Insured Vehicle No	: SFC3188K	Accident Date	: 27/12/2022
TP Vehicle No	: SBA4K	Assignment Date	: 03/01/2023
Make	: TOYOTA NOAH	Est. Duration of Repair	: 5
Date of Inspection	: 04/01/2023		
Inspection At	: TROPICAL SUCCESS AUTO CARE		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,715.00
Revised Amount	:S\$	3,940.50
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,940.50
Lump Sum Repair	:S\$	3,150.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : The above survey was conducted on a 'Without Prejudice' basis. Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.