



凱摩哆服務 KAI MOTOR TRADING

BLK 3007 UBI ROAD 1 #01-440, SINGAPORE 408701.
TEL: 6747 4006 FAX: 6743 7591 EMAIL: kaimotor@gmail.com
BUS. REG. NO: 44223100L GST NO: M90371531Y

專業服務：汽車意外保險賠償，拖車，汽車修理及維修服務，打嗎呷，噴漆。
Specialist in: Accidents Insurance Claim, Towing Service, Motor Vehicle Repairing, Panel Beating, Spray Painting.

(yan) LKK → 67418434
10:00AM

Date : 29/12/2022

Attn: The Motor Claims Department
Your Insured veh no : SKU5058K
AUTO & GENERAL INSURANCE (SINGAPORE) PTE LTD
Singapore Shopping Centre
190 Clemenceau Avenue #03-01
Singapore 239924

WITHOUT PREJUDICE

(By Email Only)

claims@budgetdirect.com.sg
Tel 62212111

Dear Sir / Madam

Estimated Cost of repair for vehicle Honda Freed SDP4711Z And SKU5058K On 19/12/2022 at 18:20pm

1pc	Rear Fender LH	1,248.30	Ry
1pc	Rear Bumper	790.30	de
1pc	Rear Bumper Lower Spoiler	568.50	de
1pc	Sport Rim	669.40	int
1pc	Rear Bumper Side Retainer LH	64.20	Xm
		3,340.70	2028.20
	Less	334.07	20% - 162.56
		3,006.63	

To dismantle & replace damage parts, panel beat where necessary
To putty, apply primer & spray paint on the affected portion.
To check wiring functions.

720.00 600
750.00 650 1280
120.00 30 2902.56
4,596.63
4/5 \$2300, 5 days

Tan Jhm 97495749/6253581
4/1/23 @ 10:15am
4/5 Resurvey after repair
Tan Jhm @ kuantan-wm
4-5 days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: