



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CS3/LPC22009402/Dvy3e2-1	
			Date: 31/01/2023	
			Code: LPC2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	XD 9070H	Veh. Inspected	SLV 1550P
	Policy No.		Coverage (\$)	0.00
	Claim No.	21/22/22/VC00/026221	Excess (\$)	0.00
	Assign From	GERALD POH	Assign Date	31/12/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	TOYOTA SIENTA	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	NHP1707098587	Colour	BLACK
	Odometer	346194 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	185/55 R15	ARIVO	4 mm
	L/H Front Tyre	185/55 R15	ARIVO	4 mm
	R/H Rear Tyre	185/55 R15	ARIVO	4 mm
	L/H Rear Tyre	185/55 R15	ARIVO	4 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	30/08/2022	Inspection Date	26/09/2022
	Survey held at	AF & CARS PTE LTD 48 TOH GUAN ROAD EAST, #01-121, ENTERPRISE HUB, SINGAPORE 608586		
<b>5a. Remarks</b>				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	