



# PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Mail Address: My Mail Box 886259 Singapore 919191

Mobile: 9295 2204 Fax: 6722 8508 Email: pasves@hotmail.com

Business Reg 201404434D

## VEHICLE INSPECTION REPORT

Report No. : PAS/TP/0410922

Date of Report : 18/10/2022

To : M/s. CLT Leasing Pte Ltd  
C/o. 48 Toh Guan Road East  
#01-121 Enterprise Hub  
Singapore 608586

Date of Assignment : 26/09/2022  
Report requested by : M/s. CLT Leasing Pte Ltd  
Date of Accident : 30/08/2022  
Date of Inspection : 26/09/2022  
Claim No. : Third Party Claim  
Policy No. : -

### PARTICULARS OF DAMAGED VEHICLE

Vehicle Registration No. : SLV1550P  
Make & Model : Toyota Sienta (Hybrid)  
Date of Registration : 22/12/2017  
Colour : Met. Black

Engine Capacity (cc) : 1496  
Mileage (km) : 346194km  
Chassis / Frame No. : NHP1707098587  
Engine No. : 1NZ8275415

### TYRE CONDITION

Front LH : 7 mm  
Make : Arivo

Front RH : 7 mm  
Make : Arivo

Rear LH : 7 mm  
Make : Arivo

Rear RH : 7 mm  
Make : Arivo

Road wheels Type : Standard

(The above represents the approximate remaining life of tyre treads)

### PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)

General Bodywork : Good  
Paintwork : Good  
Handbrake : Serviceable  
Footbrake : Serviceable  
Steering : Serviceable  
Apparent Engine Modification : Nil

### PLACE OF REPAIRER OFFICE/WORKSHOP

Location : M/s. AF & Cars Pte Ltd  
48, Toh Guan Road East, #01-121, Enterprise Hub, Singapore 608586

### ASSESSMENT

Repairer's Estimate : \$ 5,622.88  
Revised Amount : \$ 4,238.43  
Less Excess : \$ -  
Recommended Reserve : \$ 3,390.00 (Lump Sum)

Estimated Normal Period of Repairs : 6 Working Days

**Disclaimer:** The information contained in this report is intended for exclusive use of the addressees (including any attachments) solely in relation to the loss occurrence in which the assessed vehicle involved. It is confidential and may be protected by legal privilege. No liability or responsibility whatsoever shall be held by PROMINENT APPRAISER SERVICES PTE LTD for any reliance on this report by any third party. If you are not the intended recipient, please contact us immediately to arrange for its return and you should not disseminate, distribute, copy any information contained herein or use of this communication is strictly prohibited.



# PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Mail Address: My Mail Box 886259 Singapore 919191.

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg 201404434D

Vehicle No : SLV1550P

Report No. : PAS/TP/0410922

## GENERAL REMARKS

WITHOUT PREJUDICE

### THE ASSIGNMENT

The survey was conducted at M/s. AF & Cars Pte Ltd, 48, Toh Guan Road East, #01-121, Enterprise Hub, Singapore 608586.

### POINT OF IMPACT

At the RHR portion. (The RHR roadwheel was also affected)

### DAMAGES

The RHR taillamp, rear bumper, RHR fender, RHR fender inner panel, RHR wheel house, RHR rim cover, etc.

*Other parts were also found damaged. (See schedule for details)*

### ADJUSTMENT / RECOMMENDATION

We have inspected thoroughly each and every item on the repairer's estimate against the actual damaged found on the vehicle. We list the breakdown of our findings and our recommendation as per schedule attached.

Our adjusted amount for the cost of repairs is SGD \$4,238.43.

### CONCLUSION

The repairer has agreed to undertake the repairs at a lump sum of SGD \$3,390.00.


This inspection was conducted entirely on a 'Without Prejudice' basis. We have not given an authorization and/or instruction to the repairer to proceed with the repairs.

We hereby reverting the matter to you for your discretion on repairs.

Assuring you of our best services always.

Yours Truly,

**Prominent Appraiser Services Pte Ltd**

  
**Andrew How**  
Automobile Appraiser  
MSAAA  
Licensed Appraiser



# PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Mail Address: My Mail Box 886259 Singapore 919191

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg: 201404434D

Vehicle No : SLV1550P

Report No. : PAS/TP/0410922

## APPRAISEMENT SCHEDULE

S/No.	Qty	Parts Descriptions	Condition	Repairer's Estimate (S\$)	Our Assessment (S\$)
1	1 pc	Taillamp RH	Grazed/Defaced	\$ 422.10	\$ 422.10 ✓
2	1 pc	Rr bumper	Dented/Broken	\$ 682.30	\$ 682.30 ✓
3	1 pc	Rr bumper side garnish RH	Broken	\$ 136.60	\$ 136.60 ✓
4	6 pcs	Rr bumper clip	Necessary	\$ 20.40	\$ 20.40 ✓
5	2 pcs	Rr bumper retainer R/L	Broken/Necessary	\$ 145.60	\$ 145.60 ✓
6	1 pc	Rr fender RH	Dented/Buckled	\$ 1,508.10	\$ 1,508.10 1366 ✓
7	1 pc	Rr fender inner panel RH	Dented/Repair	\$ 832.60	\$ X-repair
8	1 pc	Rr rim cover RH	Grazed/Defaced	\$ 162.80	\$ 162.80 X NN
9	1 pc	Rr fender inner panel RH	Dented/Repair	(Refer labour no. 2, 5 & 6)	
10	1 pc	Rr fender wheel house RH	Dented/Repair	(Refer labour no. 2, 5 & 6)	
				\$ 3,910.50	\$ 3,077.90
				Less Discount : 25%	25%
				\$ 977.63	\$ 769.48
				List Parts Sub-Total :	\$ 2,308.43
1	1 pc	Rr tyre RH (Depreciate 20%)	Cut	\$ 250.00	\$ 200.00 X NN
2	1 pc	Rr quarter glass sealant RH	Necessary	\$ 50.00	\$ 40.00 ✓
3	1 pc	Rr fender panel sealant RH	Necessary	\$ 50.00	\$ 40.00 ✓
				Special Nett Sub-Total :	\$ 280.00
				Parts Total :	\$ 3,282.88
					\$ 2,588.43





# PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Mail Address: My Mail Box 886259 Singapore 919191

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No : SLV1550P

Report No. : PAS/TP/0410922

S/No. Labour Descriptions

Repairer's Estimate (S\$) Our Assessment (S\$)

- |   |  |             |               |
|---|--|-------------|---------------|
| 1 | To remove and reinstall electrical wiring system for necessary repairs.<br>To check affected electrical wiring system. | \$ 50.00    | \$ 30.00 ✓    |
| 2 | To remove and reinstall RHR interior trims, garnishes, seats, etc. for necessary repairs.                              | \$ 100.00   | \$ 80.00 ✓    |
| 3 | To remove and reinstall RHR quarter glass for necessary repairs.   | \$ 100.00   | \$ 80.00 ✓    |
| 4 | To conduct wheel alignment.  | \$ 60.00    | \$ 60.00 ✗    |
| 5 | To straighten, repair, realign on affected area and replace damaged parts.   | \$ 1,000.00 | \$ 770.00 ✓   |
| 6 | To spray painting, blending on affected and adjacent area.   | \$ 1,000.00 | \$ 600.00 500 |
| 7 | To spray anti-rust coating on new and affected panels.   | \$ 30.00    | \$ 30.00 ✓    |

Labour Total : \$ 2,340.00 \$ 1,650.00

Total (Parts & Labour) : \$ 5,622.88 \$ 4,238.43

3649.75

6 days

## For Lump Sum Repairs

L/S - 2919.80  
= 2900

The final adjusted Lump Sum contract amount is \$ 3,390.00

Under normal circumstances, the repairs should be completed within a reasonable period

of 6 Working Days. (Exclude waiting days of PRI, Sunday, Public Holiday and awaiting of shipment for spare parts)

16 Photographs were taken at the time of inspection.

**N.B:** By accepting to carry out the repairs on a contract Lump Sum basis, the repairer shall have the prerogative and discretion to replace the damaged parts with new, used, OEM or reconditioned parts and/or to repair the vehicle on a roadworthy condition to the entire satisfaction of owner.



