

C L APPRAISER PTE LTD

Blk 416 Pasir Ris Dr 6 #08-235, Singapore 510416
Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783
Reg No: 201000228E

INVOICE

Shaikh Ahmad Bin Shaikh Mohsin Alkhatib
C/o: ESL Automotive Pte Ltd
25 Kaki Bukit Road 4
#07-47 & #07-75 Synergy@KB, Singapore 417800

Invoice No. : CL/220551

Ref No. : ESL/10/2202/TP

Date : 8 November 2022

DESCRIPTION	AMOUNT
OUR SERVICE FEE CHARGES:	
- SURVEY INSPECTION FOR VEHICLE NO. <u>SJQ 8857 J</u> - RESURVEY INSPECTION - DIGITAL PHOTOGRAPHS SERVICES (INCLUSIVE OF STORAGE AND SUBMISSION OF DIGITAL PHOTOGRAPHS) - TRANSPORTATION	
GRAND TOTAL	S\$ 643.00

E & O. E

Notes / Payment method:

All cheque payment should be "Crossed" and made payable to " C L APPRAISER PTE LTD "

Bank Transfer -

Account Name : C L APPRAISER PTE LTD

Account Number : 588041152001

Bank : OCBC

We shall be grateful if you could forward our payment at your early convenience.



CL Appraiser Pte Ltd



Blk 416 Pasir Ris Dr 6 #08-235, Singapore 510416
Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783
Reg No: 201000228E

VEHICLE INSPECTION REPORT

To: Shaikh Ahmad Bin Shaikh Mohsin Alkhatib
C/o: ESL Automotive Pte Ltd
25 Kaki Bukit Road 4
#07-47 & #07-75 Synergy@KB, Singapore 417800

Date : 8 November 2022
Our ref : ESL/10/2202/TP

Accident Date : 25 October 2022
Inspection Date : 28 October 2022
Repairer Name : ESL Automotive Pte Ltd
25 Kaki Bukit Road 4
#07-47 & #07-75 Synergy@KB, Singapore 417800

Type of Survey : Third Party

PARTICULARS OF VEHICLE

Registration No : SJQ 8857 J
Make / Model : Hyundai Avante
Chassis No : KMH DU41BR9U771621
Engine No : G4FC9U661930

Year / Capacity : 2009 / 1591 cc
Colour : Black
Mileage : 377329

CONDITION OF TYRES

	Make	Size	Thread Balance	Rim
Front Nearside	Westlake	205/65 R16	5 mm	Sport
Front Offside	Westlake	205/65 R16	5 mm	Sport
Rear Nearside	Westlake	205/65 R16	5 mm	Sport
Rear Offside	Westlake	205/65 R16	5 mm	Sport

GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the n/s front portion.
(Details refer to the photographs attached)

Enclosed number of photographs: 83 copies

REMARKS

This inspection was conducted entirely on a "**WITHOUT PREJUDICE**" basis and we have not given authorization and instruction to the repairer to proceed with the repair.

RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a **Lump Sum of \$7,200.00** on a contractual basis.

Under normal circumstances, the repair period would be about 7 (Seven) working days.

Vehicle Registration No.: SJQ 8857 J

Our Ref No.:

ESL/10/2202/TP

Qty	Description	Conditions	Repairer's Estimate	Revised Amount
-----	-------------	------------	---------------------	----------------

SPARE PARTS - LIST ITEMS

1	Front bonnet	Damage	\$	1,102.00	\$	1,102.00	1021	✓
1	Front bonnet rubber	Necessary	\$	42.00	\$	42.00		✓
1	Front n/s headlamp	Damage	\$	481.60	\$	481.60		✓
1	Front grille	Repair	\$	385.00			×	nn
1	Front bumper	Damage	\$	480.60	\$	480.60		✓
1	Front bumper lower grille	Damage	\$	58.80	\$	58.80	×	nn
1	Front bumper reinforcement	Intact	\$	431.50			×	nn
1	Front bumper n/s side retainer	Necessary	\$	42.20	\$	42.20		✓
1	Front n/s fender	Damage	\$	385.10	\$	385.10		✓
1	Front n/s fender inner shield	Damage	\$	89.60	\$	89.60		✓
1	Front support panel	Damage	\$	985.00	\$	985.00	783	✓
1	Front shock absorber (1 set) (LH only)	Damage	\$	689.00	\$	689.00	344.50	
1	Front n/s tie rod	Damage	\$	145.00	\$	145.00	×	nn
1	Front lower arm	Damage	\$	302.00	\$	302.00		✓
1	Front n/s door	Repair	\$	1,165.20			×	R
			\$	6,784.60	\$	4,802.90	3971.60	
			Less 10%	\$	678.46	\$	480.29	-20%
Total Cost - List Items			\$	6,106.14	\$	4,322.61	3177.28	

SPECIAL NETT ITEMS

1	Front bumper clip (1 set)	Necessary	\$ 60.00	\$ 60.00	30
1	Front bumper lower spoiler	Damage	\$ 680.00	\$ 680.00	X nn
1	Front fender inner shield clip (1 set)	Necessary	\$ 40.00	\$ 40.00	20
1	Front n/s tyre (Depreciation)	Damage	\$ 400.00	\$ 200.00	X nn
1	Front n/s wheel rim	Damage	\$ 850.00	\$ 850.00	300
Total Cost - Special Nett items			\$ 2,030.00	\$ 1,830.00	350

Total cost of parts

\$ 8,136.14 \$ 6,152.61

Vehicle Registration No.: SJQ 8857 J

Our Ref No.: ESL/10/2202/TP

S/No	Description	Repairer's Estimate	Revised Amount
	Total cost of parts c/f	\$ 8,136.14	\$ 6,152.61

LABOUR

1	To check wiring , lighting and resetting headlamps focusing.	\$ 80.00	\$ 50.00 30
2	To remove and refit front undercarriage.	\$ 250.00	\$ 200.00 ✓
3	To conduct wheel alignment.	\$ 150.00	\$ 120.00 80
4	To apply undercoating on repaired and replaced panel.	\$ 180.00	\$ 120.00 30
5	To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld ; re-align body structure and damaged consistent to the accident.	\$ 1,500.00	\$ 1,250.00 1000
6	To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident.	\$ 1,400.00	\$ 1,100.00 800

GRAND TOTAL	\$ 11,696.14	\$ 8,992.61	2140
--------------------	---------------------	--------------------	-------------

5667.28

L/S - 4533.82
= 4550

7 days

Vehicle Registration No.: SJQ 8857 J

Our Ref No.: ESL/10/2202/TP

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a **Lump Sum Repair Contract of : \$ 7,200.00**

By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notified the company within seven (7) from the date hereof. Otherwise, the revised amount shall be deemed to be valid.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in other legal proceedings.

C L APPRAISER PTE LTD



Cheong K.H
Automotive Appraiser