

ASS. REP. BY: REP: CS/TP23000063/Awy3

210K

Pending for customer code

YONG TENG PTE LTD

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 12 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted: Vehicle: IN / OUT

Veh No: GBK51242 Regn: 2029 August

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Dyac c.c 2982

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 162529 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: KDY2318042-170

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: N/A S/Rim / STD A/Rim or

Tyre Size: F: 195 R15C Goform

R: 155 R13 Yokohama

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. 13/12/22 D.O.I. 15/12/22

Survey held at JL Perfect

Des. of Damages: Frt / Rear O/S / N/S / U/O / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP ECICS
21/03/2023	Confirm L/S \$15,100 @ 12 days (Red \$32,650/68%)
	MV:
	PV:
	Nett:

Date/Time, File Pass to?

21/03/2023

1) typist

Date/Time, File Return to?

2)

☐ : Prel. Report

☒ : Final Report

Days Of Repair: 12

Resurvey No. of Trip:

Survey Fee:

Transportation:

8 + RS: \$

Photos

Others

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Insp (\$)

Report Forwards: Independent

L/S \$15,100

37x15=555

170+555
50
50+50+50
185
1110

980 058 22/2/23