

COMFORTDELGRO
ENGINEERING

Our Job Ref No : 305541220
Date : 07.02.2023

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969

FINALIZATION FORM

To : LKK
Attn : NAZ
Vehicle Reg No. : SHC7055K

Fax :

29.12.2022

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-


1. The repair job shall bill to: INCOME SLF4010X
2. The finalized amount shall be:
- (a) Spare Parts after List discount \$21,134.16
- (b) Labour Charges \$2,020.00 \$1,770.00
- Total for Part-By-Part Repair Cost** \$23,154.16 \$22,904.16
- (c.) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: _____
Final Lumpsum Repair cost _____


3. Estimated normal period for repairs: 5 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
Name : CHIANG
Tel : 62148314
Fax : 65468156

Signature : 
Name : NAZ LKK
Date : 1/3/2023

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	-	N		
3. Survey Fees	-	-		
4. LTA Search Fee	\$26.75/\$2.00	YES		
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010070
 ADDRESS : CITYCAB PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65551188

JOB NO : 305541220
 REGN NO : SHC7055K
 MILEAGE : 0000000000
 MAKE : BYD
 MODEL : NEW E6
 DATE OF REGN : 26.08.2022
 DATE/TIME IN : 29.12.2022 23:30
 ACCIDENT DATE : 29.12.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0401-0033-G	REAR BUMPER UPPER BODY	1	3,301.87	20.00	2,641.50	/CRK
0002	04-01-0401-0034-G	REAR BUMPER LOWER BODY	1	2,013.75	20.00	1,611.00	/CRK
0003	28-01-0401-0018-A	RR DOOR RH LINE STICKER C	1	80.00	10.00	72.00	/NEC
0004	28-01-9999-2035-A	ZIG BOOK NOW APP LOGO REA	1	30.00	10.00	27.00	/NEC
0005	04-01-0401-0019-G	E6 LOGO	1	38.00	20.00	30.40	/NEC
0006	04-01-0401-0057-G	REAR RETRO REFLECTOR RH	1	48.00	20.00	38.40	/CRK
0007	04-01-0401-0054-G	REAR FOG LAMP	1	375.00	20.00	300.00	/CRK
0008	09-01-0401-0002-G	ON-BOARD CHARGER ASSY	1	20215.20	20.00	16172.16	/DEF
()	04-01-0401-0067-G	MIDDLE BRIGHT TRIM STRIP	1	184.00	20.00	147.20	/CRK
0010	20-01-0401-0001-G	COOLANT(DRIVE MOTOR)-5L	1	105.00	10.00	94.50	/NEC

SUB-TOTAL : 21,134.16

JOB NATURE

20,940.656

0000 PB PANEL BEATING SHC7055k TP

1200.00

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010070
ADDRESS : CITYCAB PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65551188

JOB NO : 305541220
REGN NO : SHC7055K
MILEAGE : 0000000000
MAKE : BYD
MODEL : NEW E6
DATE OF REGN : 26.08.2022
DATE/TIME IN : 29.12.2022 23:3
ACCIDENT DATE : 29.12.2022

JOB / PARTS DESCRIPTION		QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0001 SP	SPRAYPAINT CHARGE	500.00				✓
0002 20-00	TUFF COAT ON AFFECTED PARTS.	40.00				✓
0003 17-01	CHECK ALL LIGHTING	30.00				✓
0004 L	RESET/DIAGNOSIE ERROR CODE	250.00				X NN
SUB-TOTAL						: 2,020.00
TOTAL						: 23,154.16

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

5 day

COMFORT DELGRO ENGINEERING

VEHICLE I SHC7055K

TYPE OF C: TP

INCOME

SURVEY B': NAZ/LKK

305541220

DATE : 29.12.2022

SUPPLEMENTARY OF PARTS AND LABOUR COSTS

DESCRIPTION	QTY	ESTIMATE	\$	REMARKS
ON BOARD CHARGING ASSY	1	/ DEF	20215.20	20.00% ✓
REAR FOG LAMP	1	/ CRK	375.00	- repeated.
TAIL GATE EMBLEM E6	1	/ NEC	38.00	- repeated.
REAR BUMPER MID TRIM	1	/ CRK	184.00	- ✓
COOLANT (DRIVE MOTOR) 5Ltr		- NEC	105.00	10.00% ✓
LABOUR				
DAIGNOSE/REST ERROR CODE	1	XNN	250.00	

CITYCAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHC7055K

DATE 29.12.2022

MAKE REG. 26.08.2022

CHIANG/INCOME

MODEL BYD

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER / CRC			\$3,301.87
1	REAR BUMPER LOWER COVER / CRC			\$2,013.75
1	REAR BUMPER REINFORCEMENT ? X SVC			\$528.75
2	REAR BUMPER REFLECTOR LH/RH / L ? X SVC		\$48.00	\$96.00
1	REAR BUMPER REVERSE LAMP / MIS			\$375.00
2	REAR BUMPER BRACKET LH / RH ? X SVC		\$24.00	\$48.00
2	REAR BUMPER RETAINER LH / RH ? X SVC		\$87.00	\$174.00
1	TAIL GATE EMBLEM 26 / NEC			\$38.00
1	REAR FLOOR PANEL ? X R			TBA
	SUB TOTAL		5,776.62	\$6,575.37
	LESS 20%			\$1,315.07
				\$5,260.30
1	REVERSE SENSOR X SVC			\$240.00
1	REAR TAIL GATE APP STICKER / NEC			\$30.00
1	BUMPER LINE STICKER / NEC X NN			\$40.00
1	REAR DOOR ELECTRIC 100 / NEC			\$80.00
				\$351.00
	Labour Charge			
	Panel Beating		1,200	\$1,800.00
	Spray Painting Charge		500	\$700.00
	Remove/Refix Upholstery			Mx \$90.00
	Tuff Coat			40 \$90.00
	Check Wiring			30 \$60.00
	TOTAL LABOUR			\$2,740.00
	ESTIMATE TOTAL			\$8,351.29
	NAZ LKK		26,175.82	
	30/12/2022 1620			
	PIP			
	3 DAYS			
	CHECK ITEM PHOTOS			
	BEFORE/AFTER PHOTOS			

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.